



0003

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

015/015

October 9, 1987

TO: Inspection and Enforcement File
FROM: Holland Shepherd/Reclamation Specialist
RE: Work Performed At Consolidation Coal Company's Emery Deep Mine, In Relation To A TDN Written On The Improved Dike In The Lower Coal Storage Yard.

On September 10, 1987, I visited the Emery Deep mine site to evaluate the recently completed construction, performed on a dike structure in the southwest, lower, coal storage yard. The dike had been reconstructed in response to a TDN written by OSM inspector Mr. Joe Funk, following an inspection conducted by Mr. Funk and I on August 19, 1987.

According to Mr. Ron Thompson of Consol, the work had been completed on September 4, 1987. My visit, on September 10, 1987, verified that the work had been completed according to the original, approved plan.

I have requested that the operator reseed the dike and reinstall Buffer Zone markers along the top of the dike. Mr. Thompson indicated to me that this work would be done this fall.

hs

cc: Sue Linner (DOGM)
Ron Thompson (Consol)