



355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Sept. 2, 1987  
9:30 a.m. to 10:00 a.m.

Permittee and/or Operators Name: Consolidation Coal Company  
Business Address: P.O. Box 527 Emery, Utah 84522  
Mine Name: Emery Deep Permit Number: ACT/015/015  
Type of Mining Activity: Underground  Surface  Other   
County: Emery  
Company Official (s): None  
State Official(s): Holland Shepherd and Lynn Kunzler  
Partial:  Complete:  Date of Last Inspection: Aug. 18 & 19, 1987  
Weather Conditions: Sunny and clear  
Acreage: Permitted 5180 Disturbed 40 Regraded 266 Seeded 266 Bonded 247  
Enforcement Action: Termination N87-9-7-3, 3 of 3

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( X )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION Sept. 2, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS:

The operator has installed and freshly painted new perimeter markers in locations where they were lacking before. During the last inspection, the inspectors advised the operator on placement of the markers to supplement those already existing. The perimeter markers demarcate disturbed from undisturbed on the bonded area of the mine site. During the previous inspection, Mr. Joe Funk of OSM wrote a TDN based on inconsistency of perimeter markers.

9. PROTECTION OF ENVIRONMENTAL VALUES:

The operator has placed wire mesh over the exposed 18 inch vent hole located in the proposed preparation plant area. The operator was given a violation for having an uncovered vent hole last inspection. Mr. Thompson indicated to me in a previous phone conversation that the violation was abated on Aug. 20, 1987. Based on this inspection, violation--N87-9-7-3, 3 of 3--will be terminated.

Copy of this Report:

Mailed to: Ron Thompson(Consol), Brian Smith(OSM)  
Given to: Joe Helfrich

Inspectors Signature and Number: Holland Shepherd #9 Date: Sept. 3, 1987