

3-6-89
7065

0025



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

SCL
gsk

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: February 10, 1989
10:00 am to 3:30 pm

Permittee and/or Operators Name: Consolidation Coal Company
Business Address: P. O. 527 Emery, Utah 84522
Mine Name: Emery Deep Permit Number: ACT/015/015
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Ron Thompson
State Official(s): David Darby
Partial: Complete: Date of Last Inspection: January 25, 1989
Weather Conditions: Cloudy, snow on ground
Acreage: Permitted 5180 Disturbed 40 Regraded 2.7 Seeded 2.7 Bonded 247
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|--|-------|-----|-------|----------|
| 1. PERMITS | () | () | () | () |
| 2. SIGNS AND MARKERS | (X) | () | () | () |
| 3. TOPSOIL | () | () | () | () |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. STREAM CHANNEL DIVERSIONS | (X) | () | () | () |
| b. DIVERSIONS | (X) | () | () | () |
| c. SEDIMENT PONDS AND IMPOUNDMENTS | (X) | () | () | (X) |
| d. OTHER SEDIMENT CONTROL MEASURES | (X) | () | () | () |
| e. SURFACE AND GROUNDWATER MONITORING | () | () | () | () |
| f. EFFLUENT LIMITATIONS | () | () | () | () |
| 5. EXPLOSIVES | () | () | (X) | () |
| 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL | () | () | () | () |
| 7. COAL PROCESSING WASTE | (X) | () | () | () |
| 8. NONCOAL WASTE | (X) | () | () | () |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | () | () | () | () |
| 10. SLIDES AND OTHER DAMAGE | () | () | () | () |
| 11. CONTEMPORANEOUS RECLAMATION | () | () | () | () |
| 12. BACKFILLING AND GRADING | () | () | () | () |
| 13. REVEGETATION | () | () | () | () |
| 14. SUBSIDENCE CONTROL | () | () | () | () |
| 15. CESSATION OF OPERATIONS | () | () | () | () |
| 16. ROADS | | | | |
| a. CONSTRUCTION | () | () | () | () |
| b. DRAINAGE CONTROLS | (X) | () | () | () |
| c. SURFACING | () | () | () | () |
| d. MAINTENANCE | () | () | () | () |
| 17. OTHER TRANSPORTATION FACILITIES | () | () | () | (X) |
| 18. SUPPORT FACILITIES | | | | |
| UTILITY INSTALLATIONS | (X) | () | () | () |

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION 2-10-89

(Comments are Numbered to Correspond with Topics Listed Above)

A fresh snow had fallen two days before the inspection. There was still some snow covering parts of the minesite. The active parts of the disturbed area appeared muddy, but cold temperatures prevented runoff during the inspection.

4. Hydrologic Balance- Sediment Control

All the sediment control ponds were inspected. None of the ponds contained water.

17. Transportation Facilities

On February 7, 1989 Consol presented plans to construct a mine portal on the east side of the permit area. Development is planned for the summer or fall of 1989. This area was examined during the inspection. The area is remote in location and barren except for the natural vegetation which consists mostly of sage brush.

Copy of this Report:

Mailed to: Ron Thompson, SCCC; Brian Smith, OSM;

Given to: Sue Linner, DOGM; Joe Helfrich, DOGM

Inspectors Signature and Number: David W. Daily #18 Date: Feb. 28, 1989