



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Permit No. ACT/015/015 Inspection Date: May 28, 1992
 Permittee and/or Operators Name: Consolidation Coal Co.
 Business Address: P.O. Box 527 City: Emery State: Utah Zip: 84522
 Mine Name: Emery Deep County: Emery State: Utah
 Type of Mining Activity: Underground Surface Other
 Company Officials: Dee Bray State Officials: Stephen J. Demczak
 Time of Inspection: 9:00 a.m. - 2:00 p.m. Partial Complete:
 Acreage: Permitted 5180 Disturbed 40 Regraded 2.7
 Seeded 2.7 Bonded 207 Date of Last Inspection: April 9, 1992
 Weather Conditions: Warm, 70's Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	(X)	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	(X)
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	(X)	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(X)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()
19. AVS Check	(X)	()	()	(X)

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 3

Permit No. ACT/015/015 Inspection Date May 28, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits -

- a. Insurance policy number 3YL945444 complies with the minimum state requirement for coverage.
- b. The bond is issued by Chubb for the amount of \$3,454,443.00.
- c. Sediment ponds were inspected on February 27, 1992 and a small seepage is still occurring at pond #6. The inspection of the pond shows a small amount of water flowing with no potential of damage.
- d. Refuse pile was inspected on February 27, 1992 and is certified.
- e. Reviewed the water monitoring data for 1st quarter and checked parameters taken with the required parameters of the permit. All required parameters were analyzed.
- f. UNPDES: The self monitoring programs showed pond #1 and #6 discharging with all parameters in compliance with the requirements.
- g. The SPCC plan was inspected on May 6, 1992 which is a company policy.
- h. Air Quality: Presently Consolidation Coal Company is in discussions with the Department of Air Quality on the requirements for receiving an Air Quality permit. Consol's view is to be grandfather in receiving a permit.

3. Topsoil -

The topsoil and subsoil piles located by pond #6 had no signs of cows. The Division recommends that fences might be needed especially in the spring to reduce the potential cattle on top of the soil piles. The position of Consol is to not install the fences and thus potentially let the cattle graze on the soil piles. Therefore, on future inspections, if grazing or signs of cattle is located on the top of the piles, an NOV will be in order.

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 3 of 3

Permit No. ACT/O15/O15 Inspection Date May 28, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

4b. Diversions -

The diversions were measured and compared with the designs in the MRP. The diversions were larger than the designs.

7. Coal Processing Waste -

The refuse pile was inspected and the pile was reshaped to drain the water off the top of the pile. Consol is presently gathering information and data to make a determination on whether a diversion ditch is needed to remove water flow above the refuse pile.

19. AVS Check -

An AVS check was made with no new changes occurring.

Copy of report:

Mailed to: Consolidation Coal Company

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Date: June 9, 1992

Inspector's Signature and Number:

Stephen J. Demczak
Stephen J. Demczak

#39