



INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/O15/O15 DATE OF INSPECTION: September 22, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The surface facility map was reviewed and a recommendation was made to remove "Future Operation Facilities" from the plan. These future plans appear that they will not be built in the NEAR future and are making the review of the plans confusing. The MRP is still under the old regulations and is the last mine in Utah with the old regulations. The mid-term review may address the changing the MRP to the R645 regulations.

The ASCA areas were also reviewed in the permit and they need to be updated to conform with the R645 regulations and terminology.

4b. Sediment Ponds and Impoundments -

The sediment ponds were inspected and showed no signs of inlet, outlet or embankment erosion. Ponds were performing as designed.

4c. Other Sediment Control Measures -

The ASCA was inspected and additional information in the MRP will be required. The one ASCA area may be required to have contemporaneous reclamation.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Consolidated Coal Company

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: September 29, 1993

Inspector's Signature and Number: \_\_\_\_\_

  
Stephen J. Demczek

#39