



State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten initials/signature

Norman H. Bangertter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

Partial: XX Complete: Exploration  
Inspection Date/Time: June 22, 1993/09:00am-01:00pm  
Date of Last Inspection: May 18 1993

Mine Name: Emery Deep County: Emery Permit Number: ACT/015/015  
Permittee and/or Operator's Name: Consolidated Coal Company  
Business Address: P. O. Box 527, Emery, UT 84522  
Type of Mining Activity: Underground XX Surface      Prep. Plant      Other       
Officials(s): State: Stephen J. Demczak Company: Steve Behling  
Federal Official(s):      Weather Conditions:       
Existing Acreage: Permitted-5180 Disturbed-40 Regraded-2.7 Seeded-2.7 Bonded-207  
Increased/Decreased: Permitted-     Disturbed-     Regraded-     Seeded-     Bonded-      
Status: Exploration/ X Active/ Inactive/ Temp Cessation/ Bond Forfeiture  
Reclamation ( Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.  
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.  
b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[XX]	[ ]	[XX]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[XX]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015 DATE OF INSPECTION: June 22, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

3. Topsoil -

There has been very little vegetation on top of the top soils. The seeding which took place 2 years ago has not been very successful. There are some grasses within the berm ditch around the topsoil pile where moisture has been concentrated and a small amount of native vegetation on the pile. The piles show no signs of wind and water erosion. The native vegetation has started to dry out under the hot sun.

4a. Diversions -

The diversion ditches have been maintained and were performing as designed. A diversion has been constructed to transport water to the new sediment pond.

4b. Sediment Ponds and Impoundments -

The catch basin by the main offices has been reconstructed and is now classified and functioning as an approved sediment pond. The sediment pond by the refuse pile had the rills removed from the inslopes.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Consolidated Coal Company

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: June 28, 1993

Inspector's Signature and Number: \_\_\_\_\_

  
Stephen J. Demczak

#39