

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION: July 19, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers -

It was recommended during the inspection that additional disturbed area boundary markers be installed around the discharge pipes for UPDES Ponds 001 and 006. Mr. Behling agreed to this.

4c. Hydrologic Balance/Other Sediment Control Measures -

It was noted during the inspection that two berms needed to be redefined; these are at the following locations:

1) the berm between the access road and the Creek going to the used equipment storage/noncoal waste disposal area. The berm was generally in good condition but needs to be touched up in one spot.

2) the berm on the South end of the refuse pile. Mr. Behling agreed to address both of these.

7. Coal Mine Waste/Refuse Piles/Impoundments -

It was observed during the inspection that mine water pond UPDES 006 had vegetation (good size bushes, probably Willow and Tamarisk) approximately 60% of the way around the inslope perimeter. After much discussion, the Operator has agreed to remove these.


13. Revegetation -

The revegetation test plot was observed. Due to the extreme lack of moisture in this area of Emery County (as all of Utah is experiencing), plant foliation is very poor.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Consolidated Coal Company Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: August 3, 1994

Inspector's Signature and Number:  #46
Peter H. Hess