

0021



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

gpt

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: Complete: X Exploration:
Inspection Date & Time: February 9, 1994, 11:30a.m. to 2:30p.m.
Date of Last Inspection: January 11, 1994

Mine Name: Emery Deep Mine County: Emery Permit Number: ACT/015/015
Permittee and/or Operator's Name: Consolidation Coal
Business Address: P. O. Box 527, Emery, UT 84522
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Steven M. Johnson and Paul Baker
Company Official(s): Kurt Larson and Steve Behling
Federal Official(s): None
Weather Conditions: Sunny, temps. in 40's
Existing Acreage: Permitted- 5180 Disturbed- 40 Regraded- 2.7 Seeded- 2.7 Bonded- 207
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION: February 9, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

3. Topsoil

The topsoil and subsoil piles were examined. Berms around topsoil pile T-2 and subsoil pile S-1 are showing wear. The north side of the T-2 berm and the southwest end of the S-1 showed the most deterioration. To avoid loss of soil, these berms must be rebuilt.

4. Hydrologic Balance

b. Sediment Ponds and impoundments

The sediment ponds were inspected. Ponds 1 and 6 are operating without apparent problems, and the others were all dry. Inlets and outlets have been kept clean.

The annual pond inspections were made on December 22, 1993 by Bruce Ware, a certified land surveyor. He found no problems other than some seepage on the south side of Pond 6.

7. Coal Mine Waste/Refuse Piles/Impoundments

The quarterly refuse pile inspections were made on December 8, 1993 by Steve Behling and certified by Ervin Anderson. There were no problems noted in the inspections.

8. Noncoal Waste

The noncoal waste storage area was full and some trash was being blown around the area of Pond 3. Consol should remove the waste from the storage area and clean up the trash that had blown out into the yard.

21. Bonding & Insurance


The insurance policy was renewed for the period January 1, 1994 to January 1, 1995. The policy will continue to be through Lumberman's Mutual Casualty Company and the policy number will remain to be 5YL 945 444. There were no changes involved.

Copy of this Report:

Mailed to: John Gefferth (CCC), Steve Behling (CCC), Marcia Petta (OSM)

Given to: Joe Helfrich, Daron Haddock (DOGM)

Inspector's Signature: _____


Steven M. Johnson #44

Date: February 10, 1994