



cc: Wayne
Joe
ACT/015/015

Consolidation Coal Company
Mid-Continent Region
12755 Olive Boulevard
St. Louis, Missouri 63141
(314) 275-2300

May 26, 1995

Mr. Daron R. Haddock
Permit Supervisor
Utah Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Re: Permit # ACT/015/015
Follow up to 1994 Annual Subsidence Survey

*Route to Daron
then file ACT/015/015 #6*

Dear Mr. Haddock:

This letter is a follow up to the 1994 Emery Mine Subsidence Monitoring Report previously submitted to your department on December 22, 1994. As stated in that report, subsidence point 88-5 experienced 0.97 feet of movement. Per the approved monitoring plan, this point required a resurvey. The results of the 4/26/95 survey are shown below:

Elevation of Point 88-5	
<u>10/94 Survey</u>	<u>4/95 Survey</u>
5,991.05	5,990.81

Since this point shows no significant movement (± 0.5 ft.) since the previous survey, it will revert back to a one year monitoring interval. However as a matter of practice it will be resurveyed 4th quarter '95 with the rest of the subsidence monitoring points. A survey was also ran to check the coordinates of reference point C-36, the results are as follows:

<u>Original coordinates</u>		<u>1994 coordinates</u>	
N	196,855.12	N	196,855.18
E	2,066,750.82	E	2,066,750.87

If you have any questions or comments, please contact me at (314) 275-2330.

Sincerely yours,

Brian D. Butts
Environmental Engineer