



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Handwritten initials

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: X Complete: Exploration:
Inspection Date & Time: July 27, 1995 10:00 am to 3:30 pm
Date of Last Inspection: 06/28/95

Mine Name: Emery Deep Mine County: Carbon Permit Number: ACT/007/016
Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P.O. Box 527, Emery, Utah 81434
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): David W. Darby
Company Official(s): Steve Behling
Federal Official(s): none
Weather Conditions: Clear, Hot
Existing Acreage: Permitted-5180 Disturbed-40 Regraded- 2.7 Seeded- 2.7 Bonded-270
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, SIGNS AND MARKERS, TOPSOIL, HYDROLOGIC BALANCE, etc.



INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION: July 27, 1995

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Tim Kirshbaum called on July 25, to tell me that the Emery Mine would be laying off the rest of their employees shutting down the fan and closing the portals. Only Steve Behling would be at the mine on a permanent status to ensure environmental compliance.

1. Permits, Change, Transfer, Renewal, Sale

Consolidation Coal Company is still in the process of updating their mineplan to comply with some deficiencies addressed in a letter from Pam Grubaugh-Littig on May 3, 1995 which requires the applicant to define proposed and existing facilities.

2. Signs and Markers

All signs and markers are properly posted at the site.

4. Hydrologic Balance

4a. Diversions

All the diversion structures were checked to ensure proper flow conditions, all were functioning properly. No water was flowing off the minesite.


4b. Sedimentation Pond

All sedimentation ponds designed to collect surface runoff were dry. Pond 001, the large mine water discharge pond was discharging. The water is also discharging from pond 004.

Copy of this Report:

Mailed to: Donna Griffin (OSM), Emery Deep Mine

Given to: Joe Helfrich, (DOGM)

Inspector's Signature:  David W. Darby #47 Date: 08-02-95