



CONSOL ENERGY™

CONSOLIDATION COAL COMPANY  
OPERATIONS GROUP # 2P.O. BOX 566  
SESSER, IL. 62884  
618-625-2041  
FAX: 618-625-6844

January 17, 2002

Mr. Daron R. Haddock  
Permit Supervisor  
Utah Division of Oil, Gas and Mining  
1594 West North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, Utah 84114-5801

Re: Permit # ACT/015/015  
2001 Annual Subsidence Survey

Dear Mr. Haddock:

Please find enclosed the 2001 Emery Mine Subsidence Monitoring Report. Subsidence Point "E" raised 0.81 feet due to surface damage of the point. Conditions in our permit requires Consol to perform a horizontal survey to any points that experience more than 0.5 feet of movement, and to complete a resurvey in 6 months. In this instance, Consol is not going to perform this work since the movement in monitoring station "E" was due to damage. It is our intention to replace the station in the future and continue the monitoring program as approved in the permit.

If you have any questions, please contact this office.

Sincerely,

Brian D. Butts P.E.  
Project Engineer

Attachments

cc: Steve Behling  
Tim Kirshbaum

RECEIVED

JAN 23 2002

DIVISION OF  
OIL, GAS AND MINING