

*ok Incoming
c/015/0015*

0015

From: "Hardy, Russell" <RussellHardy@consolenergy.com>
To: <ogmcoal@utah.gov>
CC: <SteveChristensen@utah.gov>, <karlhouskeeper@utah.gov>, <waynewestern@ut...>
Date: 3/26/2008 2:58 PM
Subject: Emery Subsidence report
Attachments: Emery Subsidence 2-2008.pdf

Attached please find the monthly subsidence report for the Emery Mine.

Thank You,
-Russell


Russell Hardy
CONSOL ENERGY
Phone: (435) 286-3513
Fax: (435) 286-3516
email: russellhardy@consolenergy.com

----- "This communication, including any attachments, may contain confidential and privileged information that is subject to the CONSOL Energy Inc.'s Business Information Protection Policy. The information is intended solely for the use of the intended recipient(s). If you are not an intended recipient, you are prohibited from any use, distribution, or copying of this communication. If you have received this communication in error, please immediately notify the sender and then delete this communication in its entirety from your system."

Consolidation Coal Emery Mine Subsidence Report for February 2008

2-19-08

Road and Power – the powerline above 8 South is starting to lean to the East. The fourth pole to the North starting at Consol Mine Road is leaning the worst. Pictures taken. PB



In this picture the leaning powerpole is the 2nd closest pole



In this picture the leaning powerpole is the closest pole

2-27-08 Panel 14 and 15 West – No change observed. BH
8 South – No change observed. BH
O North – No change observed. BH


2-28-08 Panel 14 West – Pictures of the spring at the dam breach were taken. PB



Spring Flow through dam breach on Carter's property

3-06-08 Panel 14 and 15 West – No change noticed. PB
8 South – No change over this area. PB
O North – No new cracks existing cracks show no changes. PB

3-13-08 Road and Power – Rocky Mountain Power fixed the pole noted in the 2-19-08 inspection. Pictures were taken.



Fixed powerline above 8 South



Base of fixed powerpole

Below is a summary of the flow data from SP-10 collected by Karla Knoop, from JBR Environmental.

Consol Emery Mine
 Panel 14th West
 Bryant No. 1
 Flow Measurements made at dam
 breach
 Measurements taken by Karla Knoop

Date	Flow (gpm)
6/13/2007	77
7/24/2007	52
8/28/2007	75
9/20/2007	69
10/19/2007	59
11/15/2007	54
12/17/07	frozen
1/15/08	Flowing under, over & through ice/snow; can't measure, but flow appears to be similar to the November flow rate.
2/26/08	67