

July 1, 1981

Inspection Memo  
to Coal File:

RE: Utah Power & Light Co.  
Church Mines  
ACT/015/017  
Emery County, Utah

On June 24, 1981, Division Reclamation Officers Jean Doutré and Tom Portle performed a partial inspection at the above-mentioned minesite. They were accompanied by Larry Guymon, project engineer for Emery Mining Company.

Ditches inspected by Sandy Pruitt and Joe Helfrich on May 15, 1981, near the parking lot had been properly maintained since the last inspection, i.e., this area had been cleared of sloughage. Trash in these ditches had also been cleaned out as requested by the inspectors at that time.

The diesel tanks that were in question have been further addressed since the last inspection. Mr. Guymon informed inspectors that this area has been approved for budgeting. Currently being scheduled in order to provide drains and cement areas in order to safely store the diesel tanks.

Near the lower materials storage pad, an erosional problem is in evidence. Water had eroded away a portion of the pad which acts to channel water into the ditch before it is conveyed down the road and ultimately into the sediment pond. Mr. Guymon committed to removing materials from this area; filling areas where erosion had occurred and riprapping the area where water from the general facility enters the main drainage ditch for this area.

No violations were warranted.

THOMAS L. PORTLE <sup>TLP</sup>  
RECLAMATION OFFICER

cc: Tom Ehmett, OSM  
Larry Guymon, Emery Mining Co.

TLP/btm

Statistics:

See Wilberg memo dated July 1, 1981  
Grant: A & E