

October 7, 1982

Inspection Memo
to Coal FileRE: Utah Power and Light Company
Church Mine
Emery Mining Corporation
ACT/015/017
Emery County, Utah


A partial inspection was performed on September 28, 1982, at the above noted mine site by David Lof, John Whitehead and Tom Munson, of the Division. They were accompanied by Val Payne of Emery Mining Corporation. The purpose of the inspection was to follow-up on the September 7, 1982 inspection.

Drop inlets and headwalls had been cleaned and were well maintained at the time of the inspection.

The area behind the bath house which was the subject of NOV 82-4-10-1 had, been cleaned of non-coal waste and the disturbed area drainage had been re-established.

Mr. Payne indicated that the plans for addressing the ponding on the eastern side of the bath house pad would be to build up the elevation on the pad with new material and to asphalt over this new material to re-establish the drainage which originally existed.

The drop drain culvert from the Deseret pad to the drop inlet at the base of the coal stockpile, had been connected as Dale Grange had indicated during the September 8, 1982 inspection.

JOHN WHITEHEAD
FIELD SPECIALIST

JW/tck

cc: Tom Ehmett, OSM
Val Payne, Emery Mining Corporation
Inspection Staff

Statistics:

See Utah Power and Light Deer Creek memo for inspection on September 29, 1982; for John Whitehead, see Hiawatha memo dated October 15, 1982.