

July 8, 1982

Inspection Memo  
to Coal File

RE: Utah Power & Light Company  
Church Mine  
ACT/015/017  
Emery County, Utah

On May 19, 1982, Division Inspector David Lof conducted a partial inspection of the above mentioned minesite. He was accompanied on the inspection by Larry Guymon of Emery Mining Company.

The entrance to the Beehive portal was partially blocked, hindering the drainage from the Beehive/Little Dove pad from entering the portal. There was also non-coal waste i.e. belting, improperly stored on the pad which was hindering runoff from entering the Beehive portal. The operator was asked to have these two problems addressed prior to the next monthly inspection.

There was non-coal waste stored near the powder and primer magazines, and scrap metal on the downslope from the main access road to the picking table. The operator was asked to have these materials consolidated.

The installation of the drop drain culverting system from the Deseret pad to the tipple pad in response to NAOC 81-4-6-4, #1 of 4, is to be initiated by June 19, 1982.

The straw bales in the diversion ditch along the side of the road to the water tank appeared to be in good condition.



DAVID LOF  
RECLAMATION OFFICER

DL/tck

cc: Tom Ehmett, OSM  
Larry Guymon, Emery Mining Company  
Inspection Staff

Statistics:  
See Skyline Mine memo dated July 7, 1982