

0007

Document Information Form

Mine Number: C/015/017

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: SEPTEMBER 20, 1983

Explanation:

INSPECTION MEMO TO COAL FILE.

cc:

File in:

C/_____, _____, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

September 20, 1983

Inspection Memo to
Coal File

RE: Utah Power and Light Company
Des-Bee-Dove Mine
ACT/015/017, Folder No. 7
Emery County, Utah

DATE: August 11, 1983
TIME: 9:15 A.M. - 2:30 P.M.
WEATHER: Intermittent thunderstorms
COMPANY OFFICIALS: Larry Guymon
STATE OFFICIALS: Ken Wyatt
ENFORCEMENT ACTION: None

Compliance with Permanent Performance Standards

771 et al Permits

Interim approval was granted in a letter from Ron Daniels dated May 11, 1978. A letter notifying the Division of the Des-Bee-Dove binwall failure was observed. Ms. Pam Grubaugh-Littig of DOGM responded to this letter on February 25, 1983 requesting additional information. This was replied to in a letter from Larry Guymon dated April 26, 1983.

817.11 Signs and Markers

Perimeter markers and the mine identification sign were posted.

817.41 - .52 Hydrologic Balance

The downslopes of the Beehive/Little Dove pad were being repaired at the time of this inspection. These downslopes had been pulled back and the conveyor remounted on concrete blocks. Work was completed to reinstall and the pad was dry with the m. Sediment removal of these are positive drainage from this pad.

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No. 0007 Date _____
In C/ 015, 017, Internal
For additional information

September 20, 1983

Inspection Memo to
Coal File

RE: Utah Power and Light Company
Des-Bee-Dove Mine
ACT/015/017, Folder No. 7
Emery County, Utah

DATE: August 11, 1983
TIME: 9:15 A.M. - 2:30 P.M.
WEATHER: Intermittent thunderstorms
COMPANY OFFICIALS: Larry Guymon
STATE OFFICIALS: Ken Wyatt
ENFORCEMENT ACTION: None

Compliance with Permanent Performance Standards

771 et al Permits

Interim approval was granted in a letter from Ron Daniels dated May 11, 1978. A letter notifying the Division of the Des-Bee-Dove binwall failure was observed. Ms. Pam Grubaugh-Littig of DOGM responded to this letter on February 25, 1983 requesting additional information. This was replied to in a letter from Larry Guymon dated April 26, 1983.

817.11 Signs and Markers

Perimeter markers and the mine identification sign were posted.

817.41 - .52 Hydrologic Balance

The downslopes of the Beehive/Little Dove pad were being repaired at the time of this inspection. These downslopes had been pulled back and the conveyor remounted on concrete blocks. Work was ongoing to reinstall and finalize the grade of this pad. The Beehive/Little Dove pad was dry with the ditch draining into the Beehive portals in good condition. Sediment accumulations in this portal were still present. The removal of these sediments was discussed with Mr. Guymon to facilitate more positive drainage from this pad.

INSPECTION MEMO TO COAL FILE
ACT/015/017
September 20, 1983
Page 2

817.52 Surface and Groundwater Monitoring

The Des-Bee-Dove Mine was issued a NPDES Permit No. UT-0023591 on April 13, 1982 with an effective date of May 13, 1982. This permit expires December 31, 1986 and allows discharge from the mine area into Grimes wash.

No surface and groundwater monitoring has been conducted since this mine is such a dry one. No groundwater has been intercepted at this time. In 1982 a small perched aquifer was encountered. This water was sampled for the duration of flow. This information was included in the 1982 Hydrologic Monitoring for the Willberg and Deer Creek Mines.

Since the entire watershed of the Church mine area flows into the sedimentation pond, no surface water has been collected. This is also due to the ephemeral nature of this canyon. To date the sediment pond has never discharged.

817.89 Disposal of Non-Coal Waste

Non-coal waste is temporarily stored in bins located on the mine area. These are periodically hauled to the UP & L Power plant for disposal in the landfill there.

817.99 Slides and Other Damage

As mentioned previously work was ongoing to repair damage on the binwall located below the Beehive/Little Dove Pad.

817.100 Contemporaneous Reclamation

UP & L plans on reclaiming sections of the old water tank access road this fall. This was discussed in previous Inspection Memos to the Coal File.

817.111 - .117 Revegetation

Other areas in need of possible revegetation include the recontoured binwall slope, areas along the new access road and sections of the downslope to the bath house pad.

KW
KEN WYATT
FIELD SPECIALIST

KW/jvb

cc: Tom Ehmett, OSM
Larry Guymon, Emery Mining Corp.
Joe Helfrich, DOGM

STATISTICS:

See Valley Camp of Utah Memo dated August 30, 1982
Grant: A & E