

August 4, 1983

Memo to Coal File:

RE: Utah Power & Light Company
Church Mines
ACT/015/017, Folder #7
Emery County, Utah

On July 13, 1983, DOGM Field Specialist, Ken Wyatt conducted a partial inspection at the Des-Bee-Dove Mines. No one from Emery Mining Company was available to accompany this inspector due to the miners' vacation. The weather was clear and hot.

Activity was on-going at the mine site, however, Dale Grange could not be found at the engineer's office on-site. Work was on-going in the bathhouse parking lot area. This area had been questioned as to ponding and erosion via NAOC #83-4-1-1. Mr. Guymon had previously indicated that the parking pad and the area around the bathhouse and warehouse was to be regraded and asphalted to promote positive drainage in this area.

Work was also observed on the Beehive/Little Dove pad. It appeared as though the conveyor had been partially removed and the slope was being regraded as per previous conversations with Mr. Guymon during the last monthly inspection. All of this work will be further examined during the next monthly inspection.

KW
KEN WYATT
FIELD SPECIALIST

KW:gl

cc: Tom Ehmett, OSM
Larry Guymon, Emery Mining Corporation
Joe Helfrich, DOGM

Statistics: Vehicle: EX 45424 - 550 miles
Per Diem: One person X two days, 2.5 hours = \$60
Grant A & E