

0012

## Document Information Form

Mine Number: C/015/017

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: MAY 24, 1983

Explanation:

INSPECTION MEMO TO COAL FILE.

cc:

File in:  
C/015, 017, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date \_\_\_\_\_ For additional information

May 24, 1983

Inspection Memo  
to Coal File:

RE: Utah Power & Light Company  
Church Mines  
ACT/015/017  
Folder No. 7  
Emery County, Utah

On May 11, 1983 Ken Wyatt Field Specialist for the Division conducted a partial inspection at the above referenced minesite. Val Payne and Dale Granger accompanied this inspector during the field tour.

At the time of this inspection the upper Beehive/Little Dove pad was drying out. Drainages in the area appeared maintained, however old conveyor belting was observed strewn over the pad and portions of the adjacent access road. This belting material is supposedly going to be rewound and shipped out to the central supply storage area. This waste belting should be stored in a controlled manner pursuant to UMC 817.89.

At the time of this inspection some waste rock was observed being temporarily stored in the northern portion of the material storage area southeast of the tipple. Plate 3-4 of the Des-Bee-Dove MRP indicates that the disturbed area drainage from the tipple area, the Deseret portal pad and the bathhouse office building pad passes through this area enroute to the sediment pond. Mr. Oviatt arrived as we were discussing this situation and indicated that these wastes had been contracted to be hauled off to the Wilberg waste rock disposal site. In the future this temporary storage of waste rock should insure that the disturbed area drainages are not impaired.

The new haul road constructed to connect the Des-Bee-Dove Mines with the Wilberg haul road is almost operational. The status of the water storage/pump house area was discussed. This facility may be used in the future by the mine. Sediment control are still being maintained in the area. The small

File in:  
 Confidential  
 Shelf  
 Expandable  
Refer to Record No 0012 Date \_\_\_\_\_  
In C/ 015, 017, Internal  
For additional information

INSPECTION MEMO TO COAL FILE

ACT/015/017

May 24, 1983

Page Two

catch basins located to collect runoff from this facility were removed during the haul road reconstruction. Straw bales have been implemented. The need for the reconstruction of these catch basins will be assessed during the next monthly inspection. No violations were warranted at this time.

KEN WYATT *KW*  
FIELD SPECIALIST

KW/lm

cc: Tom Ehmett, OSM  
Larry Guymon, Emery Mining Corp.  
Joe Helfrich, DOGM  
Mary Boucek, DOGM

Statistics:

See Valley Camp Belina #1 Mine memo dated May 31, 1983.  
Grant: A & E