

0020

## Document Information Form

Mine Number: C/015/017

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: JANUARY 21, 1983

Explanation:

INSPECTION MEMO TO COAL FILE.

cc:

File in:  
C/ 015, 017, Internal

Refer to:  
 Confidential  
 Shelf  
 Expandable

Date \_\_\_\_\_ For additional information

January 21, 1983

Inspection Memo  
to Coal File:

#17

RE: Utah Power & Light Company  
Church Mine  
ACT/015/017  
Emery County, Utah

A partial inspection was conducted at the above-mentioned minesite on November 23, 1982 by David Lof of the Division. I was accompanied on the inspection by Larry Guymon and Dale Grange of Emery Mining Corporation. At the time of the inspection, there were trace amounts of snow on the ground at the minesite.

A considerable amount of conveyor belting was strewn about the Little Dove Mine pad somewhat obstructing the drainage from this area into the Beehive Portal. Mr. Guymon has indicated in the past that when belting is being replaced in the mine, the old belting is brought out onto the pad and is left there until a time at which they can get the equipment up to the pad to roll the old belting up and remove it.

Some erosion was noted on the downslope from the small pad by the Primer Magazine to the Beehive-Little Dove access road. The operator was asked to establish controlled drainage off of the magazine pad to the road below in order to control the erosion. The operator was asked to have this completed prior to the next monthly inspection.

While looking at the disturbed area runoff inlet on the coal stockpile pad, I noted that the berm on the east side of the inlet did not abut the headwall. The operator was asked to better establish the berm in order to assure that the runoff would be properly conveyed into the inlet prior to the next monthly inspection.

Some work had been done along the curb on the east side of the parking lot in order to keep runoff from the parking lot from draining down the fill slope below and causing erosion problems.

The disturbed area runoff diversion behind the bathhouse which had been the subject of NOV 82-4-10-1 had some used tires placed in it. The operator was asked to have these removed immediately.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No. 0020 Date \_\_\_\_\_

In C/ 015, 017, Internal

For additional information

INSPECTION MEMO TO COAL FILE  
ACT/015/017  
January 21, 1983  
Page 2

Straw bale dikes located at the end of the curve in the mine access road just above the old pumphouse had been properly maintained since the last inspection.



DAVID LOF  
FIELD SPECIALIST

cc: Tom Emmett, OSM  
Joe Helfirch

DL/btb

Statistics:

Vehicle: #EX 70237--418 miles  
Per Diem: 1 person X 1 days, 9.5 hours = \$50.78  
Grant: A & E