

0024

*File*

May 2, 1985

TO: Coal File, Inspection and Enforcement Folder  
FROM: Sandy Pruitt, Mining Field Specialist *SP*  
RE: Deer Creek Mine, Utah Power and Light Company, ACT/015/018,  
Folder #7, Emery County, Utah

A partial inspection of the Deer Creek Mine site was conducted by Sandy Pruitt accompanied by Larry Guymon on April 24, 1985. The inspection concentrated on the conveyor corridor.

Since winter, Emery Mining Corporation has reconstructed the water bars across the conveyor maintenance road, replaced the silt fences and maintained riprap at the discharge points. Two water bars on the upper section of the C-1 conveyor need to be extended underneath the conveyor to intercept all or runoff under the conveyor.

The tin shield installed at the conveyor rollover before the transfer station still needs to be extended to cover the rollers. There was no sign of coal deposition in the undisturbed drainage ditch since the ditch was cleaned out and the berm raised.

No compliance problems were detected on this inspection.

re

cc: Donna Griffin, OSM  
Larry Guymon, Emery Mining Corp.  
Joe Helfrich, DOGM

Statistics:

Vehicle: EX49611, 679 miles  
Per Diem: 1 person X 57 hours = \$101.90  
Grant: A&E  
0242Q-3