

0008



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

RE 2-2-87

*File*

*gh*

*gn*

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: February 12, 1987  
@ 8:30 a.m.

Permittee and/or Operators Name: Utah Power & Light / Mining Division  
Business Address: P.O. Box 310 Huntington, Utah 84528  
Mine Name: Des-Bee-Dove Permit Number: ACT/015/017  
Type of Mining Activity: Underground Yes Surface \_\_\_ Other \_\_\_  
County: Emery  
Company Official (s): Val Poyne  
State Official(s): Phil Ralphs  
Partial: Yes Complete: No Date of Last Inspection: 01/15/87  
Weather Conditions: Snowing  
Acreage: Permitted 2847 Disturbed 74.5 Regraded \_\_\_ Seeded \_\_\_ Bonded 74.5  
Enforcement Action: None

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( X )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( X )	( )	( )	( X )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/017

DATE OF INSPECTION: 02/12/87

(Comments are Numbered to Correspond with Topics Listed Above)

4. b)&c) Diversions & Sediment Ponds:

At the time of this inspection some runoff was occurring as a result of the wet snow. All runoff was being routed to the sediment pond via diversions.

The concrete energy dissipation box on the Tipple-yard pad has extraneous material in it. This material consists of mine timbers and rocks. The reason for this is because a rock overhang above the box was blasted recently (the mine timbers were placed in the box to protect it from damage). The rock was blasted because it was thought to be a possible safety hazard. The box, which also serves as a culvert inlet, was still functional and Mr. Payne said that they were planning to remove this material in the near future.

15.) Cessation of Operations:

It was announced last Friday (Feb. 6), by UP&L, that this mine will be "idled indefinitely". Mr. Payne said that they were in the process of notifying the Division of a Temporary Cessation of activities as a result of the announcement.

The Operator is planning to remove most of the equipment and materials from this site. The equipment and materials will be relocated to the Operators other two mine sites, or stored at their Central Warehouse which is located near Orangeville, Utah. At the time of the inspection the main activity consisted of moving materials and equipment. Mr. Payne and I discussed the importance of making sure the site was left in good maintenance following the cleanup and removal activities.

Copy of this Report:

Mailed to: Donna Griffin (OSM) & Val Payne (UP&L)  
Given to: Joe Helfrich & John Whitehead

Inspectors Signature and Number: Philip M. Ralston #10 Date: 02/23/87