



1407 West North Temple
P.O. Box 899
Salt Lake City, Utah 84110

RECEIVED
OCT 31 1988

Division of
OIL, GAS & MINING

October 28, 1988

Mr. John Whitehead, Permit Supervisor
Division of Oil, Gas & Mining
State of Utah
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Mr. Whitehead:

The following information addresses concerns raised by the Division regarding the Des-Bee-Dove Mine mid-term review.

UMC 784.13 - Reclamation Plan: General Requirements

See page 4-4.1 10/28/88 for response.

UMC 784.14 - Reclamation Plan: Protection of Hydrologic Balance (TM)

Delete pages 2-71 thru 2-97 and replace with pages 2-71 thru 2-76 dated 10/28/88. This reflects the conclusion of the meeting with you, Tom Munson and me.

Delete Map 2-11 "Spring Map" Drawing No. CE-10404-EM revised 10/18/83, and Map 2-10 "Hydrology Data Map of the Des-Bee-Dove Mine Permit Area" Drawing No. CE-10503-DS revised 11/2/83. Add the following maps:

<u>Map No.</u>	<u>Title</u>	<u>Drawing No.</u>	<u>Date</u>
2-10	Hydrology Data Map	CE-10478-EM	6/24/88
2-10A	Spring Map	CE-10404-EM	6/24/88
2-10B	Spring Map With Five Year Overlay	CE-10404-EM	6/27/88
2-11	Blind Canyon & Cottonwood In-Mine Water Monitoring Locations	CE-10533-DR	9/4/86
2-11A	Hiawatha Coal Seam In-Mine Water Monitoring Locations	CE-10532-WB	9/4/86

Mr. John Whitehead, Permit Supervisor
October 28, 1988
Page 2

UMC 817.44 - Hydrologic Balance: Stream Channel Diversion (TM)

Delete Map 4-1 Drawing No. CM-10393-05, Sheet 2 of 5 revised 7/11/88, and replace with pre-existing map dated 11/28/83. This material was submitted July 11, 1988 as a mid-term review response. Damage to the discharge culvert will be repaired by November 30, 1988.

Sincerely,



David Smaldone
Director of Permitting,
Compliance & Services
Mining Division

DS:bb:6102
Enclosure