



AUGUST 26, 1999

Ms. Pamela Grubaugh-Littig
Permit Supervisor
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

Dear Ms. Grubaugh-Littig:

I am enclosing for submittal the 2nd QUARTER 1999 Engineering Inspection Reports for Cottonwood/Wilberg/Des Bee Dove old Waste Rock Site and the Deer Creek Elk Canyon/Original Site. The reports were inadvertently left out of the July 21, 1999 submittal. The inspections were completed on the date indicated.


Sincerely,

John Christensen, P.E.
Sr. Construction Engineer

Encls.

cc J. Blake Webster

ACT/015/017 #6
Copy ACT/015/019 #6



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Page 1 of 3	
Permit Number	ACT/015/0017/ACT/015/019	Report Date	JUNE 21, 1999
Mine Name	Cottonwood/Wilberg/Des-Bee-Dove		
Company Name	Energy West Mining Company		
Excess Spoil Pile or Refuse Pile Identification	Pile Name	Old Waste Rock Site	
	Pile Number		
	MSHA ID Number	42-01944 & 42-00988	
Inspection Date	JUNE 17, 1999		
Inspected By	John Christensen/Rick Cullum		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		1999 2ND Quarter Inspection	
		Attachments to Report? <input type="checkbox"/> No <input type="checkbox"/> Yes	
Field Evaluation			
1. Foundation preparation, including the removal of all organic material and topsoil. Constructed according to plan.			
2. Placement of underdrains and protective filter systems. Not applicable.			
3. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established.			

4. Placement and compaction of fill materials.

This site is complete and at capacity.

5. Final grading and revegetation of fill.

Site is complete and vegetation has been established.

6. Appearances of instability, structural weakness, and other hazardous conditions.

None observed.

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

No changes in the site have occurred since the last inspection.

**Certification
Statement**



I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: JOHN CHRISTENSEN, SR. CONST. ENG.
(Full Name and Title)

Signature: *John Christensen* Date: 8/27/99

P.E. Number & State: 165651 Utah