

0027



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Handwritten initials

INSPECTION REPORT

Partial Complete XXX Exploration
Inspection Date: 06/26/2002 / Time: 8:21AM-10:54AM
Date of Last Inspection: 05/29/2002

Mine Name: Des Bee Dove Mine County: Emery Permit Number: C/015/017
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 310, Huntington, Utah 84528
Company Official(s): Dennis Oakley, Guy Davis
State Official(s): Jim Smith Federal Official(s): None
Weather Conditions: Warm, high clouds
Type of Mining Activity: Underground XXX Surface Prep Plant Other
Existing Acreage: Permitted 2760 Disturbed 24 Regraded Seeded
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows 1-21 listing various permit conditions and their evaluation status.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/017

DATE OF INSPECTION: 06/26/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

2. SIGNS AND MARKERS

Shooters have vandalized the signs. The sign at the Sedimentation Pond road is barely legible. Because these signs must remain until bond release, either regular maintenance or a long-term solution is needed.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sedimentation pond is still at maximum sediment level and needs sediment removed to provide needed capacity for runoff and sediment from precipitation. Mr. Oakley said a contractor was being hired to do the work.


19. AVS CHECK

An AVS check for Energy West – PacifiCorp was done for Cottonwood/Wilberg mid-term. There were no outstanding violations.

20. AIR QUALITY PERMIT

This operation has no air quality permit as it has not been an active mine since the 1980's.

Inspector's Signature: _____


James D. Smith # 43

Date: July 1, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Chuck Semborski, PacifiCorp
Price Field office

O:\015017.DBD\Compliance\2002\p_0626.doc