



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340 telephone
(801) 359-3940 fax
(801) 538-7223 TTY
www.nr.utah.gov

Michael O. Leavitt
Governor
Robert L. Morgan
Executive Director
Lowell P. Braxton
Division Director

0074

Handwritten initials

INSPECTION REPORT

Partial XXX Complete ___ Exploration ___
Inspection Date: 12/19/2002 / Time: 8:45 AM to 10:35 AM
Date of Last Inspection: 11/19/2002

Mine Name: Des Bee Dove Mine County: Emery Permit Number: C/015/017
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 310, Huntington, Utah 84528
Company Official(s): Dennis Oakley
State Official(s): James D. Smith Federal Official(s): None
Weather Conditions: Cold, clear, calm, four-inches of snow on the ground
Type of Mining Activity: Underground XXX Surface ___ Prep Plant ___ Other ___
Existing Acreage: Permitted 154.86 Disturbed 24 Regraded ___ Seeded ___
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Contains 21 rows of inspection items with checkboxes.



INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/017

DATE OF INSPECTION: 12.19.2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

2. SIGNS AND MARKERS

The disturbed area boundary markers above the sedimentation pond and adjacent to the county road need to be checked for placement; some appear to be within the road right-of-way. Additional markers may be needed. There is no immediate mining or reclamation activity planned for this area and no expectation of impacts impinging on this boundary, so the Permittee was told relocating or installing markers, if needed, can wait until the ground thaws.


11. CONTEMPORANEOUS RECLAMATION

The Permittee has not done contemporaneous reclamation, so this is merely a comment and not an inspection evaluation. During late November, the Division's AML program reclaimed 1.7 acres abutting but outside the permit area, where there had been pre-law spillage or storage of coal adjacent to the entry road. Several other smaller coal-spills located away from the permit area boundary were also reclaimed at the same time.

21. BONDING AND INSURANCE

The company with which the Des-Bee-Dove Mine was previously bonded, St Paul Fire and Insurance Company, will no longer be providing bonding, so PacifiCorp has arranged a new bond with Traveler's Casualty and Surety Company of America. The new bond was signed on November 18, 2002 by Judi Johansen, executive vice-president of PacifiCorp. As of the inspection date, the Division had not released the St Paul bond, so PacifiCorp was actually covered by two bonds. The new bond is for \$1,837, 712, the same as the old bond.

Inspector's Signature: _____


James D. Smith # 43

Date: December 20, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Chuck Semborski, PacifiCorp
Price Field office
O:\015017.DBD\Compliance\2002\p_1219.doc