

0001

November 26, 1979

Inspection Memo
to Coal File:

RE: Utah Power & Light Company
Deer Creek Mine
ACT/015/018A

The above mentioned mine was inspected on November 5, 1979 by Mike Thompson, Doug Stewart and Joe Helfrich from the State Division of Oil, Gas and Mining and Eileen Dougherty and Jim Dederick from the Office of Surface Mining. The inspectors and technical staff were accompanied by Karl Gurr, Senior Mining Engineer for Utah Power and Light Company.

Previous violations from the Office of Surface Mining on June 7, 1979:

1. Failure to maintain access and haul roads, and associated bridges, culverts, ditches and road right-of-ways.
2. Failure to post or posting inadequate signs.

Abatement measures taken as of November 5, 1979 inspection:

1. The lower haul road below the sediment pond is not properly bermed, therefore, no abatement was given on this violation.
2. Signs are properly placed with adequate information.

Mike Thompson also noted two areas of concern, see letter to Karl D. Gurr dated November 8, 1979.

JOSEPH C. HELFRICH *JCH*
RECLAMATION OFFICER

cc: Murray Smith

Statistics:

Vehicle # EX 68804 - 649 Miles
Vehicle # EX 68805 - 436 Miles
1,085 TOTAL MILES

Per Diem:

Jim Smith \$ 72.86
Joe Helfrich \$ 69.72
Doug Stewart \$139.02
Mike Thompson \$ 69.72

TOTAL \$251.32

JCH/te