

0011



United States Department of the Interior
OFFICE OF SURFACE MINING
Reclamation and Enforcement
[REDACTED] Brooks Towers
1020-15th Street
DENVER, COLORADO 80202

Joe
Jeh

April 4, 1980

Mr. Ron Daniels
Coordinator of Mined Land Development
Department of Natural Resources
1588 North West Temple
Salt Lake City, Utah 84116

Dear Mr. Daniels:

Enclosed please find copies of on-site inspection reports. The inspections were conducted within Deer Creek Mine during the period of March 12, 1980.

If you have any questions or problems, please contact this office.

Sincerely,

Murray T. Smith
Chief, Division of Inspection & Enforcement

REGION V ON-SITE INSPECTION REPORT

UTAH POWER AND LIGHT COMPANY
DEER CREEK MINE
P.O. Box 680
Huntington, Utah 84528
(801) 350-3535

DATE: March 12, 1980
TIME: 3:00 p.m.
WEATHER: Sunny and warm
COUNTY AND STATE: Emery County, Utah
COMPANY OFFICIALS: Dennis Killian and Tim Gwyther
STATE OFFICIALS: Joe Helfrich and Doug Stewart
OSM OFFICIALS: Larry Damrau and Tom Anderson
STATE PERMIT NO: ACT/015/018
MSHA I.D. NUMBER: 42-00121
FEDERAL ENFORCEMENT
ACTIONS: NOV #79-V-5-10, NOV #79-V-5-11, NOV #80-5-18-8,
(all violations terminated following this inspection).

A follow-up inspection was conducted to evaluate the remedial actions taken by the company to abate NOV #80-5-18-8, violation #1 of 1, (failure to maintain conveyor facilities to prevent additional contributions of suspended solids to streamflow).

Berms had been constructed to divert all surface drainage from the stockpile area into a sedimentation control pond. Diversion structures had also been constructed above the affected area to divert all unaffected drainage around the coal stockpile area. The small area immediately adjacent to the conveyor facilities had been worked to prevent surface drainage from the area from entering Deer Creek.

The violation was terminated following the inspection.


LARRY DAMRAU
RECLAMATION SPECIALIST