

0001

QUARTERLY ENGINEERING REPORT
DEER CREEK SEDIMENTATION POND
December 31, 1981

INTRODUCTION

This report is submitted in compliance with
Federal and State Regulations:

UMC 817.46 (t)
UMC 817.49 (h)
30 CFR 77.216-3

Monitoring Procedures: The four monitoring points were checked during
the inspection and no settlement or displacement has occurred.

Elevations: Top of Dam: 7236.54
Toe of Dam: 7216.61
Top of Impounded Water: 7218.39

Existing Storage Capacity: Ice covered the ponds, therefore, no cross-
sections were taken.

General: A visual inspection of the facility was made. No signs of
structural weakness, erosion or other hazardous conditions were found.

I do hereby certify that I am a
registered Professional Engineer
in the State of Utah holding
current license #5214 and do also
certify that the above report is
true and correct to the best of
my knowledge.

Larry J. Guymon Date 12-31-81
Larry J. Guymon, P.E.
#5214

QUARTERLY ENGINEERING REPORT
DEER CREEK SEDIMENTATION POND

October 31, 1981

INTRODUCTION

This report is submitted in compliance with
Federal and State Regulations:

UMC 817.46 (t)
UMC 817.49 (h)
30 CFR 77.216-3

Monitoring Procedures: The four monitoring points were checked during
the inspection and no settlement or displacement has occurred.


Elevations: Top of Dam: 7236.54
Toe of Dam: 7216.61
Top of Impounded Water: 7218.50

Existing Storage Capacity: 11.99 acre feet

General: A visual inspection of the facility was made. No signs of
structural weakness, erosion or other hazardous conditions were found.

Since the last quarterly inspection was made, some maintenance work
has been done in the under drain pipe.

I do hereby certify that I am a
registered Professional Engineer
in the State of Utah holding
current license #5214 and do also
certify that the above report is
true and correct to the best of
my knowledge.

 Date 10-31-81
Larry J. Guymon, P.E.
#5214

QUARTERLY ENGINEERING REPORT

DEER CREEK SEDIMENTATION POND

July 21, 1981

INTRODUCTION

This report is submitted in compliance with
Federal and State Regulations.

UMC 817.46 (t)
UMC 817.49 (h)
30 CFR 77.216-3

Monitoring Procedures: The four monitoring points were checked during
the inspection and no settlement or displacement has occurred.

Elevations: Top of Dam: 7236.54
Toe of Dam: 7216.61
Top of Impounded Water: 7217.72

Existing Storage Capacity: 12.15 acre feet

General: A visual inspection of the facility was made. No signs of
structural weakness, erosion or other hazardous conditions were found.

Since the last quarterly inspection was made, some maintenance work
has been done in the under drain pipe.

I do hereby certify that I am a
registered Professional Engineer
in the State of Utah holding
current license #5214 and do also
certify that the above report is
true and correct to the best of
my knowledge.

Larry J. Guymon Date 7-21-81
Larry J. Guymon, P. E.
#5214

QUARTERLY ENGINEERING REPORT

DEER CREEK SEDIMENTATION POND

May 4, 1981

INTRODUCTION

This report is submitted in compliance with
Federal Regulations:

UMC 817.46(t)
UMC 817.49(h)
30 CFR 77.216-3


Monitoring Procedures: The four monitoring points were checked during
the inspection and no settlement or displacement has occurred.

Elevations: Top Of Dam: 7236.54
Toe Of Dam: 7216.61
Top Of Impounded Water: 7216.8

Existing Storage Capacity: 12.22 Acre Feet

General: A visual inspection of the facility was made. No signs of
structural weakness, erosion or other hazardous conditions were found.

I do hereby certify that I am a
registered Professional Engineer
in the State of Utah holding cur-
rent license #5214 and do also
certify that the above report is
true and correct to the best of
my knowledge.


Larry J. Guyton, P.E.
#5214

Date 5-11-81

QUARTERLY ENGINEERING REPORT

DEER CREEK SEDIMENTATION POND

INTRODUCTION

This report is submitted in compliance with federal regulations:

UMC 817.46(t)
UMC 817.49(h)
30 CFR 77.216-3


Monitoring Procedures: A series of five points have been established, four of which are located on the dam embankment and one adjacent to the dam for a reference point. Coordinates and elevations have been established on each point. Four times per year these points will be checked to monitor any movement or settlement of the dam embankment.

Elevations: Top of dam: 7236.54
Upstream toe of dam: 7216.61
Top of impounded water: 7216.61

Existing Storage Capacity: Because of the ice cover on the pond, no cross-sections were attainable, therefore, the storage capacity is not available for this report.

General: A visual inspection was made of the facility. No signs of structural weakness, erosion or other hazardous conditions were found; and no fires have occurred in the dam embankment or excess material piles.

I do hereby certify that I am a registered Professional Engineer in the State of Utah holding current license #5214 and do also certify that the above report is true and correct to the best of my knowledge.


Larry J. Guymon, P. E. #5214