

0007

July 1, 1981

Inspection Memo
to Coal File:

RE: Deer Creek Mine
Utah Power & Light Co.
ACT/O15/O18A
Emery County, Utah

On June 24, 1981, Division Reclamation Officers Jean Doutre and Tom Portle visited the Deer Creek minesite. They were accompanied by Larry Guymon, project engineer for Emery Mining Company.

Since the last inspection, a berm has been erected by the diesel tank in the upper portion of the operation near the water tank and diversion. This area had been reworked with a berm which provides an enclosure or impoundment capable of holding the total amount of diesel fuel contained within this tank in the event of a rupture.

Other work that had been done since the inspection was implementation of both buffer zone signs and perimeter markers. These were on site, clearly visible on the upper portion of the operation.

In the parking area near the drop drains, a culvert had been crushed in places and was no longer functioning as intended. New culvert material was in place in proximity to this and work had been scheduled to employ this new culvert.

No violations were warranted.

THOMAS L. PORTLE ⁷⁴¹
RECLAMATION OFFICER

cc: Tom Ehmett, OSM
Larry Guymon, Emery Mining Co.

TLP/btm

Statistics:

See Wilberg memo dated July 1, 1981
Grant: A & E