

November 7, 1984

TO: Coal File, Inspection & Enforcement Folder  
FROM: Sandy Pruitt, Mining Field Specialist. *SP*  
RE: Utah Power and Light Company, Deer Creek Mine,  
ACT/015/018, Folder #7, Emery County, Utah

A partial inspection of the Deer Creek Mine was conducted by Sandy Pruitt and Ken Wyatt on October 30, 1984. Larry Guymon accompanied inspectors on a brief tour of the mine site.

Compliance on site was good. Of concern was the condition of the silt fences installed along the conveyer and at the lower material storage yard. Although protection was provided by the silt fences, due to the poor installation there is a potential for heavy runoff to cut around the silt fence. This was pointed out to Larry Guymon who committed to repair the situation within the next week.

Mr. Guymon reported that following the strike, Emery Mining Company still intended to maintain the diversion terrace above the ROM conveyor and to seed the leachfield site this fall. On the record, additional areas that should be seeded are the downslopes of the access road adjacent to the conveyor line below the sediment pond, the sewage line along the west side of the access road and the flume site.

kc

cc: Donna Griffin, OSM  
Joe Helfrich, DOGM  
Larry Guymon, Emery Mining Company

Statistics: See Soldier Creek Mine Memo dated November 5, 1984

05710-8