

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION: 6/27/96

(Comments are Numbered to Correspond with Topics Listed Above)

Rilda Canyon Surface Facilities

Some rip-rap had been placed in the drainage. The rip-rap had not been graded with the smaller component missing. Smaller material will need to be added.

Some material had been placed outside the berm and creek side although still on the pad. The operator removed the material during the inspection with no problems noted. The operator was reminded that all material must be contained within the berm.

The operator was urged again to finalize the road and pad drainage.

Copy of this Report:

Mailed to: OSM, Richard Northrup (PacifiCorp)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: *Susan M. White*

#35 Date: 7/31/96