



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Handwritten initials and 'OK' mark

INSPECTION REPORT

Partial XXX Complete ___ Exploration ___
Inspection Date: 12/09/2002 Time: 9:00am-4:30pm
Date of Last Inspection: 11/14/2002

Mine Name: Deer Creek Mine County: Emery Permit Number: C/015/018
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 310, Huntington, Utah 84528
Company Official(s): Ken Fleck
State Official(s): Stephen J. Demczak Federal Official(s): Steve Falk (BLM)
Weather Conditions: Cool, 20's
Type of Mining Activity: Underground XXX Surface ___ Prep Plant ___ Other ___
Existing Acreage: Permitted 19075.70 Disturbed 95.79 Regraded ___ Seeded ___
Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, SIGNS AND MARKERS, TOPSOIL, HYDROLOGIC BALANCE, etc.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/018

DATE OF INSPECTION: 12/09/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES


The silt fences along the road to the mine were spot-checked and did comply with the performance standards. Some fences did contain a small amount of water.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The majority of the inspection was underground at Deer Creek. The areas that were inspected underground were 9th east, 9th east sub-mains, and 10th east section. The BLM and DOGM inspectors were looking for greases, oils, and lubricants, which could, in time, contaminate ground water. The permittee plans to seal this area in the near future. The material list was given to the inspectors on what would be left behind; the seal and materials will be removed before sealing is completed. The areas mentioned above, contained mostly steel, old belting, power cables, and plastic and steel pipe. Cans of WD40 were found and removed during the inspection, also one gallon of oil lubricant. There were pumps and power centers still operating during the inspection; these are to be removed in the near future. In summary, there were no apparent hazardous materials being left behind.

8. NONCOAL WASTE

The area was generally clear of non-coal waste material.

Inspector's Signature:  Date December 11, 2002
Stephen J. Demczak #39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Chuck Semborski, PacifiCorp
Price Field office

O:\015018.DER\Compliance\2002\p_1209.doc