

February 15, 1983

Inspection Memo  
to Coal File:

RE: Utah Power & Light Company  
Wilberg Mine  
ACT/015/018-B  
Emery County, Utah

On December 23, 1982 a partial inspection was conducted at the above mentioned minesite by Division Inspector David Lof. He was accompanied on the inspection by Paul Peterson of Emery Mining Corporation. The purpose of the inspection was to follow up on NOV N82-4-16-1 and several other areas of concern discussed with the operator during the December 8th and 9th, 1982 complete inspection.

NOV N82-4-16-1 was issued for failure to meet State and Federal effluent limitation standards for discharge from disturbed areas and failure to maintain their approved sediment ponds. The operator had been given one week (3:30 P.M on December 16, 1982) in order to have the sediment ponds properly maintained to insure that State and Federal effluent limitation standards would be met. At the time of this inspection there was no discharge from the sediment ponds, the sediment ponds had been cleaned out with a backhoe and the material placed in the waste rock disposal site. At the time of the inspection a portion of the outlet on the upper cell of the sediment pond was being repaired.

Other areas of concern checked on during the inspection:

- A. The slotted drain across the road to the portals was being cleaned out.
- B. The disturbed area runoff inlet on the east side of the access road above the upper parking lot pad still needed to be cleaned out.
- C. The berm and undisturbed diversion around the lower parking lot pad were properly maintained.

  
DAVID LOF  
FIELD SPECIALIST

DL/lm

cc: Tom Ehmett, OSM  
Larry Guymon, Emery Mining Corporation  
Joe Helfrich, DOGM

Statistics:

See Price River Coal Complex memo, date February 15, 1983.