

0023

File

August 27, 1985

TO: Coal File, Inspection and Enforcement Folder
FROM: Sandy Pruitt, Mining Field Specialist *SP*
RE: Wilberg/Cottonwood Mine Complex, Utah Power and Light
Company, ACT/015/019, Folder #7, Emery County, Utah

A partial inspection of the above mentioned complex was conducted by Sandy Pruitt on August 16, 1985.

The Cottonwood Portal was briefly inspected. New mine identification signs identifying the Cottonwood Mine Project, ACT/015/019 and the new MSHA I. D. number were posted above and below the project permit area. All sediment ponds appeared adequate. The road drainage culvert inlet below the discharge point from the south sediment pond and located at the base of the lower mine identification sign was crushed. This section of the road is privately owned and leased to Utah Power and Light Company (UP&L) so the culvert is UP&L's responsibility. Therefore, NOV #N85-2-15-1 was warranted for the failure to maintain road drainage systems to function as designed, UMC 817.165. The remedial action of this NOV requires repair of the culvert to function as designed within two weeks or no later than September 6, 1985.

The waste rock disposal site was also inspected at this time. Cell #3 was overflowing with waste rock material. Excavation of Cell #5 had not been initiated yet. The mine identification sign at the waste rock disposal site has an incorrect permit identification number (ACT/015/019 instead of ACT/015/018).

re

cc: Donna Griffin, OSM
Larry Guymon, EMC
Joe Helfrich, DOGM

Statistics: See Skyline mine memo dated August 23, 1985.
0292Q-37