

8-24 JB

0012



Handwritten initials/signature in the top right corner.

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangert  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
901-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Aug. 17, 1988  
10:00-11:30 a.m.

Permittee and/or Operators Name: Utah Power & Light Mining Division  
Business Address: P.O. Box 310 Huntington, Utah 84528  
Mine Name: Wilberg/Cottonwood Permit Number: ACT/015/019 715<sup>5</sup>  
Type of Mining Activity: Underground  Surface  Other  
County: Emery State: Utah  
Company Official(s): Guy Davis  
State Official(s): Bill Warmack and Rick Smith  
Partial:  Complete:  Date of Last Inspection: July 19, 1988  
Weather Conditions:  
Acreage: Permitted 11508 Disturbed 42.5 Regraded      Seeded      Bonded 42.5  
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION Aug. 17, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Guy Davis (UP&L) and Rick Smith (DOGM) accompanied the undersigned inspector during this partial inspection. Mine site conditions were dry; no erosion problems were noted. Follow-up maintenance issues are listed for reference and do not constitute a violation of the UMC standards.

2. SIGNS AND MARKERS:

The perimeter marker at the northern end of the material yard has been replaced.

4b. DIVERSIONS:

The diversion below the guard shack has been riprapped to provide additional sediment control. This should reduce the amount of sediment that currently reports to the silt fence.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

The flow meter on pond #1 was being installed during this inspection and will be operable per previous requests.

4d. OTHER SEDIMENT CONTROLS:

1. The silt fence below the guard shack was in good repair; however, material from the previous cleaning was still evident above the fence and will be removed by August 31, 1988.
2. Silt fences by the Cottonwood conveyor have been repaired. An assessment of the area by the Cottonwood fan should be done to determine whether sufficient vegetation is present to eliminate the use of silt fences.
3. The silt fence below the tipple has been installed per the previous request; however, some additional enhancement work still needs to be done and will be completed by August 31, 1988.

Copy of this Report:

Mailed to: Val Payne, UP&L

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: July 21, 1988