



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

*pgk  
gck*

## INSPECTION REPORT

INSPECTION DATE & TIME: 12:30 to 15:00, 23 January 1992

Permittee and/or Operator's Name: PacifiCorp Electric Operations  
 Business Address: 210 S Main, Suite 2100, SLC, Utah 84140-0021  
 Mine Name: Cottonwood-Wilberg Permit Number: ACT/015/019  
 Type of Mining Activity: Underground: X Surface:     Other:      
 County: Emery State: Utah  
 Company Official(s): Jerald Pollack (PacifiCorp-HFO)  
 State Officials(s): Hugh Klein (DOGM)  
 Federal Official(s): NA  
 Partial: X Complete:     Date of last Inspection: 11 Dec. 1991  
 Weather Conditions: Clear and mild, -3°C  
 Acreage:  
 Permitted: 11532 Disturbed: 102 Regraded:     Seeded:     Bonded: 102  
 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	(X)
2. SIGNS AND MARKERS	(X)	( )	( )	(X)
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	(X)
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	(X)	( )	( )	(X)
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	( )	( )	(X)

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

Permit Number ACT/015/019

Date of Inspection 23 January 1992

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

As Guy Davis (PEO) was not available at the time of inspection, I was accompanied by Jerald Pollack (PEO). When asked, Mr. Pollack declined the opportunity to view my credentials.

1)

The PAP states that the owner is:

Utah Power and Light Company (UP&L)  
1407 West North Temple  
SLC, Utah 84116

and that the operator is:

UP&L, Mining Division  
Post Office Box 310  
Huntington, Utah 84528

The permit sign at the mine states the owner is:

PacifiCorp Electric Operations  
201 South Main Street Suite 2100  
SLC, Utah 84140-0021

and that the operator is:

Energy West  
Post Office Box 310  
Huntington, Utah 84528

This information was collected for the purpose of an AVS check.

2)

All permit signs and markers were in place and clearly visible.

4b)

In general, diversions were found to be free of debris. A few ditches were observed to contain ice and snow. Running water was seen in diversions leading to the sediment ponds. The diversion at the east side of the employee parking lot was being cleaned of ice during the inspection.

4c)

Both the North and South Pond were receiving and discharging water. Ice was present in both ponds and the water level in both structures was below the drop inlets.

**INSPECTION REPORT**

(Continuation sheet)

Page 3 of 3

Permit Number ACT/015/019

Date of Inspection 23 January 1992

4d)

Silt fences were observed to be functional and well kept.

13)

The test plots exhibited no noticeable erosion. Erosion netting was in place. Minor vegetation was observed, but there does not appear to have been any significant moisture in the recent past.

18)

Storage pads were found to be well kept. In one area on the upper pad, ice and snow were beginning to form over a drop drain. This was brought to the operator's attention.

Copy of this Report:

Mailed to: Blake Webster (PEO-SLC)

Guy Davis (PEO-HFO)

Bernie Freeman (OSM-AFO)

Given to: Joe Helfrich (Utah DOGM)

Inspector's Signature & Number:  #40

Date: 27 January 1992