


0027



June 2, 1999

Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801

ACT/015/018 #2
ACT/015/017 #2
ACT/015/019 #2
COPY JOE

Attention: Jim Smith

Re: Revised Volume 9 Hydrologic Section, PacifiCorp, Des-Bee-Dove mines, ACT/015/017, Deer Creek Mine, ACT/015/018, Cottonwood Mine, ACT/015/019

PacifiCorp, by and through its wholly-owned subsidiary, Energy West Mining Company ("Energy West") as mine operator, hereby submits a revised Volume 9 Hydrologic Section for the following mines: Cottonwood Mine Act/015/019, Deer Creek Mine Act/015/018 and Des-Bee-Dove mines Act/015/017 in response to concerns raised during our meeting on May 26, 1999.

The concerns raised during the review include:

Concern: **R645-301-712,-731.700.** HM-5 is certified by an AIPG certified professional geologist: AIPG certification does not meet the requirements of the Utah Coal Mining Rules...

Response: **Map HM-5 has been certified by a professional engineer.**

Concern: **R645-301-724.300.** It is stated on page 81 that the relationship of Little Bear Spring to Mill Fork graben is shown on HM-6: the location of Little Bear Spring is on HM-6, which is a reproduction of a USGS map, but HM-6 does not show the faults or graben. HM-7 shows the relationship of the spring to the graben.

Response: **Page 81 has been revised to state: "As illustrated on HM-7, Little Bear Spring is directly in line with the western edge of the graben.....".**

Concern: **R645-301-121.200, 724.** Even-numbered pages in the copy of the report by Ecosystem Research Institute in Hydrologic Support Information 3 were copied off-center and text and numbers .

Huntington Office:
(435) 687-9821
Fax (435) 687-2695
Purchasing Fax (435) 687-9092

Deer Creek Mine:
(435) 687-2317
Fax (435) 687-2285

Trail Mountain Mine:
(435) 748-2140
Fax (435) 748-5125

DOGM Volume 9 Revisions

Page Two

June 2, 1999

Response: **Reproduction error, enclosed is 10 copies to be inserted in Hydrologic Support Information #3.**

Concern: **R645-301-121,200, -724.300.** The PHC refers to section R645-301-722 for data used to arrive at the conclusions of the PHC (p. 128).

Response: **Text on page 128 has been revised to correctly state "Data utilized to arrive at the conclusions presented in this section were discussed earlier (see Section R645-301-721)....."**

Enclosed is seven copies of the following information for your review:

Revisions to Volume 9 - Hydrologic Section:

Volume 9 HYDROLOGY

- ∞ *Replace Map HM-5 (certification did not meet the requirements of the Utah Coal Mining Rules).*
- ∞ *Replace text section pages 81-82 and 127-128 (revised to address the concerns listed above).*
- ∞ *Replace Hydrologic Support Information #3 (Reproduction error).*

If you have any questions or concerns regarding this submittal, please feel free to contact myself at 687-4720 or Dennis Oakley at 687-4825.

Sincerely,



Charles A. Semborski
Geology/Permitting Supervisor

CAS/cas

cc: Blake Webster (InterWest Mining Company)
Carl Pollastro (Energy West Mining Company)
Dennis Oakley (Energy West Mining Company)

I:\PCCOMMON\PCCOMMON\ENVIRONM\PERMITS\EMHYDRO\VOL9REV.699

I:\PCCOMMON\PCCOMMON\ENVIRONM\PERMITS\EMHYDRO\VOL9REV.699