

0041



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

gh *pgl*

INSPECTION REPORT

INSPECTION DATE & TIME: 1030 to 1230, 29 October 1991
 Permittee and/or Operator's Name: Co-Op Mining Company
 Business Address: Post Office Box 300, Huntington, Utah 84528
 Mine Name: Bear Canyon Permit Number: ACT/015/025
 Type of Mining Activity: Underground X Surface Other
 County: Emery State: Utah
 Company Official(s): Charles Reynolds
 State Officials(s): Hugh Klein (DOGM)
 Federal Official(s): N/A
 Partial: X Complete Date of last Inspection: 26 September 1991
 Weather Conditions: Overcast, cold (28° F) and snowing
 Acreage: Permitted 1060 Disturbed 16 Regraded Seeded Bonded 16
 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(x)	()	()	(x)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(x)	()	()	(x)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(x)	()	()	(x)
d. OTHER SEDIMENT CONTROL MEASURES	(x)	()	()	(x)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(x)	()	()	(x)

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/025 DATE OF INSPECTION: 29 October 1991

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

1)

Mine permit signs were noted as being in the proper location and containing the requisite information.

3)

Approximately two inches of snow were covering the topsoil pile. The perimeter berm at the base of the topsoil pile was observed to be in good condition.

4c)

Sediment pond A was found to be partially frozen over. Despite the snow and cold temperatures, there was some runoff reporting to the pond.

4d)

The discharge pipe into Bear Creek had been re-oriented so as to discharge into the 60 inch culvert in the direction of flow. In doing so, the operator has ensured protection of the upstream bank from erosion.


18)

At some point in the past, the operator constructed a concrete splash pad under the refueling tank spigots. The pad is sloped bank to the tanks so any minor fuel spillage or leakage will drain back to the tanks instead of onto the ground. This work is appreciated as it will minimize the potential for these fuels to migrate into the subsurface.

Copy of this Report:

Mailed to: Bernie Freeman (OSM)
Wendell Owen (Co-Op)
Given to: Joe Helfrich (DOGM)
Pam Grubaugh-Littig (DOGM)

Inspector's Signature & Number: _____
Date: _____



#40

1 November 1991