



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

pgl
gch

Norman H. Bangerter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 09:00 to 11:00, 10 February 1992

Permittee and/or Operator's Name: Co-Op Mining Company

Business Address: Post Office Box 1245, Huntington, Utah 84528

Mine Name: Bear Canyon Permit Number: ACT/015/025

Type of Mining Activity: Underground: X Surface: Other:

County: Emery State: Utah

Company Official(s): Marlow Petersen (Co-Op)

State Official(s): Hugh Klein (DOGM)

Federal Official(s): NA

Partial: X Complete: Date of last Inspection: 17 Dec. 1991

Weather Conditions: snowing, approximately 1" on the ground, 3°C

Acres:

Permitted: 1060 Disturbed: 16 Regraded: Seeded: Bonded: 16

Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

Permit Number ACT/015/025

Date of Inspection 10 February 1992

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

Charles Reynolds (Co-Op/MEC) was unavailable at the time of inspection, so I was accompanied by Marlow Petersen (Co-Op). When asked if he wished to review my credentials, Mr. Petersen declined.

3)

A large portion of the topsoil pile was covered by snow. The berm around the perimeter of the pile was in good condition. Nothing else noteworthy was observed.

4b)

Diversions appeared in good working condition. Almost all diversions were snow covered, so a detailed inspection was not possible.

4c)

Water in both ponds (A and B) was not taking up a large amount of storage capacity. It is estimated that the ponds were filled to 10 or 15% capacity. The surface of both ponds was covered by snow and ice.

4d)

The Hoist Road Catch Basin was inspected and found to be maintained as required in the PAP.

13)

Snow was covering the entire baseball field, but a great deal of the grass was long enough so as the blades were penetrating through the snow.

Copy of this Report:

Mailed to: Bernie Freeman (OSM-AFO)

Wendell Owen (Co-Op)

Given to: Joe Helfrich (DOGM)

William Malencik (DOGM-PFO)

Inspector's Signature & Number: *Mark St. K.* #40

Date: 11 February 1992