

0040



State of Utah  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor

Ted Stewart  
Executive Director

James W. Carter  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340  
801-359-3940 (Fax)  
801-538-5319 (TDD)

July 7, 1993

CERTIFIED RETURN RECEIPT REQUESTED  
P 074 975 430

Mr. Wendell Owen  
Co-Op Mining Company  
P.O. Box 1245  
Huntington, Utah 84528

*Wendell*

Dear Mr. Owen:

Re: Division Order and Mid-Term, Co-Op Mining Company, Bear Canyon Mine,  
ACT/015/025-DO-93A, Folder #3, Emery County, Utah

Enclosed please find a Division Order and Finding of Permit Deficiency for the Bear Canyon Mine. This Division Order is a consequence of the mid-term review for the Bear Canyon Mine. If in your review of this order you have any questions, please call me or Pamela Grubaugh-Littig, Permit Supervisor.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Lowell P. Braxton'.

Lowell P. Braxton  
Associate Director, Mining

jbe  
Enclosure  
cc/enc: J. Helfrich  
P. Grubaugh-Littig  
J. Kelley  
A:\DOLTR,93A



STATE OF UTAH  
DIVISION OF OIL, GAS AND MINING

---

PERMITTEE

Wendell Owen  
Bear Canyon Mine  
Co-Op Mining Company  
P.O. Box 1245  
Huntington, Utah 84528

ORDER & FINDINGS  
of  
PERMIT DEFICIENCY

PERMIT NUMBER ACT/015/025  
DIVISION ORDER # 93A

---

PURSUANT to R645-303-212, the DIVISION ORDERS the PERMITTEE, Co-Op Mining Company, to make the permit changes enumerated in the findings of permit deficiency in order to be in compliance with the State Coal Program. These findings of permit deficiency are to be remedied in accordance with R645-303-220.

FINDINGS OF PERMIT DEFICIENCY

The Division finds the permit deficient in that the reclamation cost estimate found on pages 3-83 through 3-90 does not contain adequate documentation of the various costs which are cited in that estimate. For example, on page 3-89, under the heading "Soil Placement and Seed-Bed Material and Handling," a total cost of \$58,480 is given. There is, however, no information as to how this cost was calculated, how much material is to be moved, or how much time this work is expected to take.

For another example, on page 3-88 under the heading "Crusher Facility," it is stated that the demolition of this structure will take 4 days. Again, however, there is no information as to how this time estimate was calculated and there is, therefore, no way of verifying the estimated reclamation cost of \$2910.84.

Regulation Cited    R645-301-542.800


Requirements

In order to comply with this regulation, the permittee must revise the reclamation cost estimate to show how the various costs were calculated. This additional information must include structure dimensions, earthwork volumes, time estimates, etc., as well as the sources of such information, whether such information is found elsewhere in the permit application package or whether it comes from other sources.

ORDER

Co-Op Mining Company is ordered to make the requisite permit changes in accordance with R645-303-220 and to submit a complete application for permit change to address the findings of permit deficiency within 30 days of date of the Order. Approval by the Division must be obtained within 60 days of date of this Order. All approvals not obtained within 60 days may result in a hindrance violation.

Ordered this 8<sup>th</sup> day of July, 1993, by the Division of Oil, Gas and Mining.

  
James W. Carter, Director  
Division of Oil, Gas and Mining