

10.4 of this report. It is doubtful that proposed expansions will seriously impact the other species sense no new surface disturbances are planned.

Birds

One species of involved birds are on the endangered species list: the peregrine falcon (thought to be a year-round resident in southeastern Utah). However, there are no known nesting sites for the peregrine falcon in this area. Because of the suspected transient nature of these birds, no problems are foreseen with the projected development. A Raptor survey was made during 1987 to confirm these assumptions. Potential areas of impact are shown on Plate 5-3A. The areas designated for potential impact include the mine site location and the haul road and utility corridor.

The more important bird species of the area are listed in Appendix 3-K.

TABLE OF CONTENTS (Continued)

CHAPTER 5 ENGINEERING

LIST OF APPENDICES

<u>APPENDIX</u>	<u>DESCRIPTION</u>	<u>PAGE</u>
Appendix A	Existing Structures.....	5A-1
Appendix B	Culinary Water System.....	5B-1
Appendix C	Subsidence Control and Monitoring.....	5C-1
Appendix D	Toxic Materials and Handling.....	5D-1
Appendix E	Surface Blasting Plan.....	5E-1
Appendix F	Mine Roads.....	5F-1
Appendix G	Tank Seam Access Road.....	5G-1
Appendix H	Slope Stability Analysis In Access Roads.....	5H-1
Appendix I	Cut and Fill Calculations.....	5I-1
Appendix J	Wild Horse Ridge – Blind Canyon Seam Pad and Conveyor Access Roads.....	5J-1
Appendix K	Wild Horse Ridge Tank Seam Access Roads.....	5K-1
Appendix L	Morhland Access Roads.....	5L-1
Appendix M	Blind Canyon Intake and Fan Portals.....	5M-1
Appendix N	Shower House Waste Disposal System.....	5N-1
Appendix O	Sediment Pond Material.....	5O-1

TABLE OF CONTENTS (Continued)

CHAPTER 5 ENGINEERING

LIST OF PLATES

<u>PLATE</u>	<u>DESCRIPTION</u>
Plate 5-1A	Bear Canyon No. 1 and No. 3 Mines (Blind Canyon Seam)
Plate 5-1B	Bear Canyon No. 1 Mine (Hiawatha Seam)
Plate 5-1C	Bear Canyon No. 2 and No. 4 Mines (Tank Seam)
Plate 5-2A	Surface Facilities (Ballpark Area)
Plate 5-2B	Surface Facilities (Shower House Area)
Plate 5-2C	Surface Facilities (Load-out Area)
Plate 5-2D	Surface Facilities (Mine Access Road Area)
Plate 5-2E	Surface Facilities (Tank Seam Portal Area)
Plate 5-2F	Surface Facilities (WHR Access Road Area)
Plate 5-2G	Surface Facilities (WHR Portal Area)
Plate 5-2H	Surface Facilities (Blind Canyon Area)
Plate 5-3	Subsidence Map
Plate 5-3A	Confidential Subsidence Map
Plate 5-4A	Road Details
Plate 5-4B	Road Details
Plate 5-4C	Road Details
Plate 5-4D	Road Details
Plate 5-5	Belt Portal Pad Details
Plate 5-6A	Post Mining Topography (Ballpark Area)
Plate 5-6B	Post Mining Topography (Shower House Area)
Plate 5-6C	Post Mining Topography (Load-out Area)

Plate 5-6D	Post Mining Topography (Mine Access Road Area)
Plate 5-6E	Post Mining Topography (Tank Seam Portal Area)
Plate 5-6F	Post Mining Topography (WHR Access Road Area)
Plate 5-6G	Post Mining Topography (WHR Portal Area)
Plate 5-7F	Pre-Mining Land Surface Configuration (WHR Access Road Area)
Plate 5-7G	Pre-Mining Land Surface Configuration (WHR Portal Area)
Plate 5-8	Cross Sections