



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil Gas and Mining

JOHN R. BAZA
Division Director

June 28, 2007

Charles Reynolds, Resident Agent
Co-Op Mining Company
P. O. Box 1245
Huntington, Utah 84528

Subject: Deficiencies for Wild Horse Ridge Tank Seam As-Built, Task ID #2811, Co-Op Mining Company, Bear Canyon Mine, C/015/0025

Dear Mr. Reynolds:


The Division has reviewed your Wild Horse Ridge Tank Seam As-Built application. The Division has determined that there are some deficiencies that must be addressed before the Division can make a determination that the requirements of the R645 Coal Mining Rules have been met and approve the amendment. Those deficiencies are listed as an attachment to this letter.

Each deficiency identifies its author by that author's initials in brackets, so that your staff can directly communicate with that individual relative to the preparation of Co-Op Mining Company's response to that particular deficiency.

[PWB] Priscilla Burton (435) 613-1146 Ext. 207
[JDS] Jim Smith, Team Lead (801) 538-5262
[WHW] Wayne H. Western (801) 538-6263

Please respond to these deficiencies as soon as possible, but no later than July 30, 2007, such that we may efficiently process your application.

Sincerely


Pam Grubaugh-Littig
Permit Supervisor

sb
Attachment
O:\015025.BCN\DRAFT\WG2811\DEF2811.DRAFT.DOC

Deficiency List
Task No. 2811
Bear Canyon Mine
Wild Horse Ridge Tank Seam As-Built

R645-301-830.110, and R645-301-140, The Permittee must update the Division's reclamation cost estimate that the Permittee incorporated into the MRP. The Division and the Permittee must use the same reclamation cost estimate for determining the bond amount. The Division will provide the Permittee with assistance as needed. [WHW]

R645-301-121.200, -121.300, The Permittee needs to include all pages indicated on the C2 form. Specifically, 5K-14 through 5K-21 and 5K-21A are listed on the C2 form but are missing from the submittal [JDS]

R645-301-121.200, -121.300, The Permittee needs to correct the pagination errors at pages 7-114 and 7-115; also pages 7-117 and 1-118 [JDS]

R645-301-741, -742.312, The Permittee needs to match the volume of discharge of C-23U indicated in the table on page 7G-50 with that on page 7G-77. [JDS]