



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 27, 1988
9 a.m. to 2 p.m.

Permittee and/or Operators Name: Genwal Coal Company
Business Address: P.O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground XX Surface Other
County: Emery
Company Official (s): Lannie Burnside and Richard Shynoweth- Surface Operators
State Official(s): Harold G. Sandbeck
Partial: XX Complete: Date of Last Inspection: June 13, 1988
Weather Conditions: Cloudy and sprinkling
Acreage: Permitted 164.4 Disturbed 5.75 Regraded 0.5 Seeded 0.5 Bonded 5.75
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(XX)	()	()	(XX)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(XX)	()	()	(XX)
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	(XX)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(XX)	()	()	(XX)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	(XX)	()	()	(XX)
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION July 27, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. Lannie Burnside and Richard Shynoweth (Surface Operator's) accompanied the undersigned inspector on this partial inspection. Mining was in progress. The bathhouse was 95% complete.

2. Signs and Markers. The operator was informed to maintain the disturbed markers by repainting the roof bolt tips and installing additional markers where needed.

4. Hydrologic Balance:

b. Diversions. The operator was informed to dress up a short section of ditch located along the road leading up to the portal pad area. This concern is a preventive maintenance item.

d. Other Sediment Control Measures.

The operator needs to place additional strawbales along the haul road for erosion protection.

The silt fences were removed, replaced or relocated. Please refer to the June 13, 1988 inspection report for additional information. The silt fences were properly installed.

8. Noncoal Waste. The operator was informed to remove debris from behind the office and along the road leading up to portal pad area. This debris is related to the bathhouse construction.

16. Roads:

c. Surfacing. The operator was controlling fugitive dust by watering down the roads.

Copy of this Report:

Mailed to: Andy King (Genwal Coal), Price Office and Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Howard J. Hansen* #27 Date: July 29, 1988