

4-14-89
7050

0015



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Jan 5/89

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: April 4, 1989
3:30 PM to 5:40 PM

Permittee and/or Operators Name: Genwal Coal Company
Business Address: P. O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Andy King
State Official(s): Rick Summers, Harold Sandbeck, Sue Linner
Partial: X Complete: Date of Last Inspection: 3/7/89
Weather Conditions: clear, wind, cold
Acreage: Permitted 164.4 Disturbed 5.15 Regraded 0.5 Seeded 0.5 Bonded 5.15
Enforcement Action: none.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION 4/4/89

(Comments are Numbered to Correspond with Topics Listed Above)

b. DIVERSIONS

The operator has been routinely maintaining the diversions at the site. A rock had recently spalled from the cliffs in the area of the powder magazine and was located partially in the undisturbed diversion at the toe. Due to the late hour of this inspection, the operator committed to moving the rock the following morning. The diversion function was not jeopardized and weather conditions indicated no potential for precipitation in the interim. The culvert that was to be installed across the access road to the sediment pond has not been installed to date. The operator was given a deadline of April 30, 1989 to install the culvert. No deadline had been established for the installation prior to this inspection.

c. SEDIMENT PONDS AND IMPOUNDMENTS

The sedimentation pond contained runoff to an elevation approximately 3 feet below the elevation of the primary spillway. An insignificant leak in the decant system (less than 0.5 gpm) will require repair. The operator was given a deadline of April 30, 1989 to conduct the necessary repairs. It was noted that the peizometer in the sediment pond embankment contained water. The silt fence located at the toe of the sediment pond embankment was inspected and the operator was given permission to remove the fence. The intent of the fence (MRP) was for sedimentation control during sediment pond construction.

d. OTHER SEDIMENT CONTROL MEASURES

The operator has placed straw bales along the outslope of the USFS Parking area. The operator was unable to stake the bales in place at the time of placement due to frozen ground conditions. The operator intends to stake the bales within a week. The bales were functional at the time of the inspection.

Copy of this Report:

Mailed to: Brian Smith - OSM Allen Childs - Genwal Coal Co.

Given to: Joe Helfrich and Susan Linner - DOGM

Inspectors Signature and Number:  #15 Date: 4/6/89