



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John SLL

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: November 30, 1989
8:00 a.m. to 4:00 p.m.

Permittee and/or Operators Name: Genwal Coal Company
Business Address: P.O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground XX Surface Other
County: Emery
Company Official (s): Jim Pruitt and Randall Ralphs
State Official(s): Harold G. Sandbeck
Partial: Complete: XXX Date of Last Inspection: 10/30/89
Weather Conditions: Clear and cold
Acreage: Permitted 164.4 Disturbed 5.75 Regraded 0.5 Seeded 0.5 Bonded 5.75
Enforcement Action: Also inspected CEP/015/032-89A

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(XX)	()	()	(XX)
2. SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	(XX)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	()	()	()
b. DIVERSIONS	(XX)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	(XX)
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(XX)	()	()	()
f. EFFLUENT LIMITATIONS	(XX)	()	()	()
5. EXPLOSIVES	(XX)	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(XX)	()	()	()
7. COAL PROCESSING WASTE	()	()	(XX)	()
8. NONCOAL WASTE	(XX)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX)	()	()	()
10. SLIDES AND OTHER DAMAGE	(XX)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(XX)	()	()	(XX)
12. BACKFILLING AND GRADING	(XX)	()	()	()
13. REVEGETATION	(XX)	()	()	()
14. SUBSIDENCE CONTROL	(XX)	()	()	()
15. CESSATION OF OPERATIONS	()	()	(XX)	()
16. ROADS				
a. CONSTRUCTION	(XX)	()	()	()
b. DRAINAGE CONTROLS	(XX)	()	()	(XX)
c. SURFACING	(XX)	()	()	()
d. MAINTENANCE	(XX)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(XX)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(XX)	()	()	()

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION 11/30/89

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. On this complete inspection, the undersigned inspector was accompanied by Jim Pruitt and Randall Ralphs. The snow cover was approximately 18 inches.

1. Permits.

Permit Stipulation Status

Stipulation UMC 784.13-(1)-JRH: The operator's response was received on December 1, 1989. The response is currently under DOGM review.

Stipulation UMC 771.23-(1)-SCL: The operator's response was received on December 1, 1989. The response is currently under DOGM review.

Stipulation UMC 817.48-(1)and(2)-JSL: The operator's response was received on September 11, 1989. Final approval was given on October 17, 1989.

Stipulation UMC 817.121-126-(1)-DWD: The operator's response was received on December 6, 1989. The response is currently under DOGM review.

Stipulation USFS-(1): The operator's response was received on November 3, 1989. Pending final approval letter from DOGM.

East Mountain Exploration Program

The reclaimed state lease exploration hole was inspected on November 2, 1989 by the undersigned inspector. The drill pad disturbance was small in size which caused minimal disturbance to the adjacent undisturbed area. The drill pad area was reclaimed.

NPDES Discharge Reports

The 1989 2nd and 3rd quarter reports were inspected. The documented small pond leak has been repaired. No other problems were noted.

4. Hydrologic Balance:

c. Sediment Ponds and Impoundments.

The 3rd quarter 1989 pond inspection report was checked. The documented small pond leak has been repaired. No other problems were noted.

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION 11/30/89

(Comments are Numbered to Correspond with Topics Listed Above)

11. Contemporaneous Reclamation.

Step Slope Irrigation Log Inspection

A Division letter dated August 8, 1988 requires the operator to irrigate the steep slope between the powder magazine pad and the trailer. This slope will be irrigated through the growing season beginning May 15th and ending September 30 of each year until ground cover is in excess of 80% (Based on annual inspections by the Division).

The irrigation log was inspected up to September 30, 1989. No problems were found.

16. Roads.

b. Drainage Controls.

A cement berm has been constructed on the south side of the access road from the reclaimed old office pad area to the west end of the truck turnaround area. The operator was cautioned to not blade snow over the access road upslope in the areas immediately below and above the cement berm.

Copy of this Report:

Mailed to: Allen Childs (Genwal Coal), Price Office and Brian Smith(OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Howard J. Hansen* #27 Date: 12/18/89