



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Dez
Joh

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Permit No. ACT/015/032 Inspection Date: July 13, 1992
Permittee and/or Operators Name: Genwal Coal Company
Business Address: P.O. Box 1201 City: Huntington State: UT Zip: 84528
Mine Name: Crandall Canyon Mine County: Emery State: Utah
Type of Mining Activity: Underground Surface Other
Company Officials: Jay Marshall State Officials: Stephen J. Demczak
Time of Inspection: 8:00 a.m. - 1:00 p.m. Partial Complete:
Acreage: Permitted 2165.42 Disturbed 5.55 Regraded 0.5
Seeded 0.5 Bonded 5.6 Date of Last Inspection: July 11, 1992
Weather Conditions: 80's Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(X)	()	()	(X)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()
19. AVS Check	()	()	()	()

Permit No. ACT/O15/O32 Inspection Date July 13, 1992(Comments are Numbered to Correspond with Topics Listed Above)3. Topsoil -

The topsoil piles were inspected and additional or replacement of straw bales will be required. The bales or even a silt fence will be required to separate road material from the topsoil pile. The upper most topsoil piles will need additional straw bales to prevent road drainage from encroaching the topsoil.

4b. Diversion -

The diversion ditch located along the road graveled to mine portal will require grading due to sediment loading. Presently not a violation but additional storms may cause non-compliance situation.

4c. Sediment Ponds and Impoundments -

The sediment pond at the mine site will require the elimination of minor erosion at the inlet of the pond. This was caused by several storms that took place during the weekend. The operator was going to add additional rip rap and cement for bonding. This would eliminate future problems.

8. Noncoal Waste -

The mine was on a two week vacation prior to Monday's inspection. The mine pad at the portals did contain empty cans and litter. The non-coal waste material have not been a problem area at this mine. The problem was remedied at once.

Copy of report:

Mailed to: Genwal Coal CompanyMailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)Filed to: PFODate: July 16, 1992Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak