

0018



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: XX Complete: Exploration:
Inspection Date & Time: 25 May, 1993/10:00 to 12:30
Date of Last Inspection: 22 April, 1993

Mine Name: Crandall Canyon Mine County: Emery Permit Number: ACT/015/032
Permittee and/or Operator's Name: Genwal Coal Company
Business Address: P. O. Box 1201, Huntington, Utah 84528
Type of Mining Activity: Underground XX Surface Prep. Plant Other
State Officials(s): James D. Smith
Company Official(s): Lannie Burnside
Federal Official(s): None
Weather Conditions: Sunny, 60's
Existing Acreage: Permitted-2165.42 Disturbed-5.55 Regraded-0.5 Seeded-0.5 Bonded-5.55
Increased/Decreased: Permitted-0 Disturbed-0 Regraded-0 Seeded-0 Bonded-0
Status: Exploration/ XX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.

## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT /015/032

DATE OF INSPECTION: May 25, 1993


(Comments are Numbered to Correspond with Topics Listed Above)

2. Disturbed area boundary markers were spot checked and only one was found to have be down, presumably from wildlife movement or snowpack during the past winter. Lannie was advised that someone from the mine should check the markers around the entire perimeter. The markers should be repainted or replaced as needed. The headgate of diversion UD-3 was checked and found to be inside the disturbed area markers.
3. Shrubs and small trees on the topsoil piles are budding and new sprouts are emerging at the base so these plants appear to be recovering from the effects of winter weather and wildlife browsing.
- 4a. Ditches were compared against design dimensions found in the MRP and were determined to be built and maintained to meet specifications.
13. Grasses are becoming well established on the road to the unused substation pad. Several thistle plants were found on the pad. New growth from reseeding around the sediment pond is still sparse but drainage from the affected area reports directly to the sed pond.

Copy of this Report:

Mailed to: Marcia Petta (OSM) Larry Johnson - Jay Marshall (Genwal Coal Company)

Given to: Joe Helfrich (DOGM) Daron Haddock (DOGM)

Inspector's Signature:  # 43 Date: 26 May, 1993