



John

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: Complete: XX Exploration
Inspection Date/Time: April 26, 1994/08:00am-03:00pm
Date of Last Inspection: March 24, 1994

Mine Name: Crandall Canyon County: Carbon Permit Number: ACT/015/032
Permittee and/or Operator's Name: Genwal Coal Company
Business Address: P.O. Box 1201, Huntington, Utah 84528
Type of Mining Activity: Underground XX Surface Prep. Plant Other
Officials(s): State: Stephen J. Demczak Company: Larry Johnson
Federal Official(s): Edzel Pugh Weather Conditions: Cool, Raining
Acreage: Permitted-2165.42 Disturbed-5.55 Regraded-.5 Seeded-.5 Bonded-5.55
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/XXXActive/ Inactive/ Temp Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[]	[XX]	[]
2. SIGNS AND MARKERS	[XX]	[]	[XX]	[]
3. TOPSOIL	[XX]	[]	[XX]	[]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[]	[XX]	[]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[]	[]	[]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[]	[]	[]
d. WATER MONITORING	[XX]	[]	[]	[]
e. EFFLUENT LIMITATIONS	[XX]	[]	[]	[]
5. EXPLOSIVES	[XX]	[]	[]	[]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	[]	[]	[]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[]	[XX]	[]	[]
8. NONCOAL WASTE	[XX]	[]	[]	[]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[XX]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	[XX]	[]	[]	[]
11. CONTEMPORANEOUS RECLAMATION	[XX]	[]	[]	[]
12. BACKFILLING AND GRADING	[XX]	[]	[]	[]
13. REVEGETATION	[XX]	[]	[]	[]
14. SUBSIDENCE CONTROL	[XX]	[]	[]	[]
15. CESSATION OF OPERATIONS	[XX]	[]	[]	[]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	[]	[]	[]
b. DRAINAGE CONTROLS	[XX]	[]	[]	[]
17. OTHER TRANSPORTATION FACILITIES	[XX]	[]	[]	[]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	[]	[]	[]
19. AVS CHECK (4th Quarter-April, May, June) <u> </u> date	[XX]	[]	[XX]	[]
20. AIR QUALITY PERMIT	[XX]	[]	[]	[]
21. BONDING & INSURANCE	[XX]	[]	[]	[]

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/O15/O32

DATE OF INSPECTION: April 26, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

- a) The permit was renewed on May 20, 1994 by both the permittee and the Division. The Reclamation Agreement was signed by both parties with the bonded amount of \$703,000.
- b) The UPDES permit will expire on August 31, 1995. The permit number is Ut 0024368. The site has two discharge locations 1) 001 - a 6-inch pipe from sediment pond and, 2) 002 - a 4-inch discharge from mine.
- c) Air Quality Permit was issued on February 3, 1992.
- d) The insurance policy (3710-39-89) Federal Insurance Co. was inspected and complies with the R645 regulations. The expiration date is January 1, 1995.
- e) The SPCC Plan was reviewed and was written on January 21, 1992. The document is P.E. certified.
- f) Water Quality parameters were checked for MW-1 and were found to be complete.
- g) Subsidence survey was taken by the operator on June 30, 1993 and is submitted in the Annual Report.
- h) The sediment ponds were annually certified on January 15, 1994.

2. Signs and Markers -

The identification signs were inspected and found to be in compliance with the R645 regulations.

3. Topsoil -

The topsoil piles were all inspected and they have the required sediment control for erosion. The piles were vegetative and no signs of erosion were apparent.

4a. Diversion -

There were two disturb diversions which were in the undisturbed area. The operator moved the disturb perimeter markers to reflect that the ditches are within the disturb area and submitted map showing the new disturb area.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Larry Johnson (Genwal Coal Company)


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: May 10, 1994

Inspector's Signature and Number:


Stephen J. Demczak

#39