



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 8/21/96 / 8:00a.m.-12:30p.m.
Date of Last Inspection: 7/18/96

Mine Name: Crandall Canyon Mine County: Emery Permit Number: ACT/015/032
Permittee and/or Operator's Name: Genwal Resources, Inc.
Business Address: P.O. Box 1210, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): None
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm, 80's
Existing Acreage: Permitted- 2165.42 Disturbed- 5.55 Regraded- .5 Seeded- .5 Bonded- 5.55
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows 1-21 list various permit conditions and their evaluation status.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 8/21/96

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The permittee has met with the Division for information and ideas about the deficiency on the creek culvert and new surface installations.

4A. DIVERSIONS -

The diversions were spot-checked and meet the requirements of the R-645 regulations. Several of the diversions were recently cleaned out.

4B. SEDIMENT POND -

The sediment pond was surveyed for sediment storage capacity. The initial overlook of the survey information from the permittee is that the pond will need to be cleaned out. The permittee has said the pond will be cleaned out, if needed.

18. SUPPORT FACILITIES -

The forest service turn-around was inspected for mining equipment and cars related to the mine operations. This was a request made by the Forest Service. The turn-around was empty during the inspection.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Genwal Resources, Inc. Marcia Petta (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: August 26, 1996

Inspector's Signature:  #39
Stephen J. Demczak