



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340
(801) 359-3940 (Fax)

Partial: XXX Complete: Exploration:

Inspection Date & Time: 7/30/97 / 7:00a.m.-1:00p.m.

Date of Last Inspection: 6/17/97

Mine Name: Crandall Canyon Mine County: Emery Permit Number: ACT/015/032
Permittee and/or Operator's Name: Genwal Resources, Inc.
Business Address: P.O. Box 1420, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Gary Gray
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm, 80's
Existing Acreage: Permitted- 5034.90 Disturbed- 5.41 Regraded- .5 Seeded- .5 Bonded- 5.41
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Contains 21 rows of inspection items with checkboxes.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 7/30/97

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The permittee has received approval from the Division to construct their new coal loadout facility. The permittee has started earth work consisting of installing two culverts to transport water. Siltation structures (silt fences) were installed within the creek as required by the amendment. The silt fences were causing sediment to drop out as designed. The permittee was saving topsoil and removing vegetation during the inspection. There were not any out of compliance issues noticed during the inspection.

4a. DIVERSIONS -

Several diversions were spot-checked and were functioning as designed. No water was flowing within the diversions during the inspection.

4b. SEDIMENT PONDS -

The sediment pond was not discharging during the inspection nor was the mine discharge pipe. There were no signs of hazardous conditions to the sediment pond. The sediment pond contains a large amount of coal fines. This problem should be less once the coal loading facility is constructed.


4c. OTHER SEDIMENT CONTROL -

Silt fences were installed within the creek at several locations to catch sediment from the construction site. It appears that the majority of the sediment was being held back by these silt fences. It is recommended the silt fences are to be checked frequently.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Gary Gray (Genwal) Henry Austin (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: August 5, 1997

Inspector's Signature:  #39
Stephen J. Demczak